

22/03/2020

ASS. REC. BY:

REF: CS3/A1920004778/G+d3/

Special Instructions:

Supervisor: Luo Qiong

ASSIGNMENT (Office)

Mentor:

From (Person): Teo Encweihong of AIGDate/Time: 01/04/2020 @ 2:17pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 5665X

Insured:

SKN 3734

at Workshop m/s

Harmony Motor

Tel:

6583 0001 / 9111 1365

of

48 Jln Guan Road east #02-113

Policy No:

800040103

Claim No:

766358423756

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/03/2020

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time: 224pm 1/4/2020

Person Contacted:

GuniceVehicle IN/OUT

Date/Time

Action/Instruction

Estimate (X)SLU 5665X - XSKN 3734 - XSubmit DRB Report24- File pass to typist

ASS. PEO. BY:

(REF)

AIG CS3 / AIG 20004778/Gtd3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Formed:

Lump Sum / L.B.R. is

☐

Preli. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Week end (\$

Survey Fee:

Transportation:

3 + PS. SI

Photos

Other:

TOTAL

FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED V...

From: Teo, Ericweihong
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Hor, Yinrul, Abu Kassim, Noor Mariesa, Subramaniam, Divyashni
Sent: 4/1/2020 2:17:32 PM
Attachments: Letter of Reject.pdf Annex A.pdf SLU5665X - PRS.pdf SLU5665X - PRS.pdf

Hi LKK,

Kindly assist on attached PRI.
Thank you.

Regards,
Eric Teo Wei Hong
AIG
Claim Adjuster II,
Singapore— Auto Express & FNOL
Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.
Tel 8001206556 | Ext: 1002213
Ericweihong.Teo@aig.com | www.aig.com

From: Teo, Ericweihong
Sent: Wednesday, April 1, 2020 2:15 PM
To: 'eunice@harmony.com.sg' <eunice@harmony.com.sg>
Cc: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKN373U AND SLU5665X ON 30/03/2020

Without Prejudice

Your Reference: SLU5665X
Our Reference : SKN373U

Dear Sir/Madam,

We refer to your email below. We disagree with the list of your nominated surveyors.
Pursuant to Appendix C of Pre-Action Protocol for NIMA cases, citation 2.9. We will proceed to appoint our appointed surveyor for the pre-repair inspection.

Thank you.

Regards,
Eric Teo Wei Hong
AIG
Claim Adjuster II,
Singapore— Auto Express & FNOL
Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.
Tel 8001206556 | Ext: 1002213
Ericweihong.Teo@aig.com | www.aig.com

From: eunice@harmony.com.sg <eunice@harmony.com.sg>
Sent: Wednesday, April 1, 2020 12:26 PM

<https://securemail2.aig.com/securereader/read.jsf>

To: Teo, Ericweihong <Ericweihong.Teo@aig.com>
Cc: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKN373U AND SLU5665X ON 30/03/2020

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

Kindly refer to the Reject Letter & Annex A as per attached.

Thank you.

Best Regards,

Eunice Chong

Harmony Motor (AMK) Pte Ltd

48 Toh Guan Road East

#02-113 Enterprise Hub

Singapore 608586

Tel : 6583 0001

Whatsapp : 9111 1365

From: Teo, Ericweihong [<mailto:Ericweihong.Teo@aig.com>]

Sent: Wednesday, April 1, 2020 10:16 AM

To: eunice@harmony.com.sg

Cc: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKN373U AND SLU5665X ON 30/03/2020

This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2020-04-07 21:15 CDT to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2019 Proofpoint, Inc. All rights reserved.

From: Ericweihong.Teo@aig.com
To: eunice@harmony.com.sg
Cc: Kok-Chong.Lim@aig.com , NoorMariesa.AbuKassim@aig.com , Yinrul.Hor@aig.com , Divyashni.Subramaniam@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKN373U AND SLU5665X ON 30/03/2020
Date: Wed, 1 Apr 2020 02:15:41 +0000
Without Prejudice

Your Reference: SLU5665X
 Our Reference : SKN373U

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.
 Thank you.

Regards,
 Eric Teo Wei Hong
 AIG

Claim Adjuster II,
Singapore— Auto Express & FNOL
Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.
Tel 8001206556 | Ext: 1002213
Ericweihong.Teo@aig.com | www.aig.com

From: eunice@harmony.com.sg <eunice@harmony.com.sg>
Sent: Tuesday, 31 March, 2020 5:29 PM
To: Lim, Sheng Yang <ShengYang.Lim@aig.com>
Subject: [EXTERNAL] Accdt involving SLU5665X \$SKN373U on 30/03/2020 along Jalan Bahar

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

Kindly refer to the PRS as per attached.

Thanks.

Best Regards,
Eunice Chong
Harmony Motor (AMK) Pte Ltd
48 Toh Guan Road East
#02-113 Enterprise Hub
Singapore 608586
Tel : 6583 0001
Whatsapp : 9111 1365

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/03/2020 14:58
Date Of Accident	30/03/2020 10:30
Exact Location Of Accident	JALAN BAHAR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU5665X
Insured/Policyholder	
Name Of Registered Owner	TEO AH CHENG
NRIC No	SXXXX746Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91455176
Alternative Phone No	OTHERS-91455176

Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5114140587 (CLASSIC)
Cover Note Number	

Driver

Name of Driver	SAM CHEW LAN
NRIC No	SXXXX800J
Date Of Birth	20/09/1972
Occupation	OUTDOOR
Date Of Driving Pass	05/03/2018
Driving Experience	2 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91990625
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 805D #12-86 KEAT HONG CLOSE KEAT HONG PRIDE
Postcode	684805
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-6659999 - FAX NO: 66655793
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	CANNOT BE UPLOADED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKN373U
Vehicle Make/Model/Colour	MERCEDES BENZ / SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEN HONGJIE
NRIC/Passport Number	SXXXX750A
Contact Number	92234299
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	SAM CHEW LAN
Approximate Age	47
Injuries Sustain	HEADACHE, BACK PAIN, SHOULDER STIFF
Injured person in which vehicle?	SLU5665X
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 805D #12-86 KEAT HONG CLOSE KEAT HONG PRIDE
Postcode	684805

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

30 MAR 2020


Reporting Centre Personnel Signature
Name:

NG WING KIN JAMES
admin.vac@vicom.com.sg

SKETCH PLAN

A) SLU5665X

B) SKN373U



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This morning around 10.30am while I was driving along PIE toward Jalan Bahar exit at Lane 5 I was hit from behind of my car by vehicle SKN 373U.

My car was at station at the point when SKN 373U hit my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

30 MAR 2020



Reporting Centre Personnel's Signature
Name: NG WING KIN JAMES
NRIC No: admin.vac@vicom.com.sg

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	746Z
Vehicle No.:	SLU5665X
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Apr 2020
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT LED EU6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	P520485652
Chassis No.:	JM6BN22A8J0193628
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,926.00
Original Registration Date:	07 Dec 2017
First Registration Date:	07 Dec 2017
Transfer Count:	1
Actual ARF Paid:	\$13,926.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Dec 2027
PARF Rebate Amount:	\$10,444.00
COE Expiry Date:	06 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,112.00
COE Rebate Amount:	\$36,182.00
Total Rebate Amount:	\$46,626.00

The information contained herein is correct as at 01 Apr 2020

OK

(01)Bent (2)Dented (3)Distorted (4)Cracked (5)Cut (6)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Replace (✓) (2)Repair (R) (3)Check (C)
(4)Not Consistent (NC)

Vehicle No: GU 5665X

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	RE	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	MIS	✓	
1146	992341	Rear Bumper Clips	RL	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	✓	
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: _____ Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Apr 2020 Edit Reg		01 Apr 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: ONG BEE CHOO , ID: S1611329H									
Main Claimant: -									
Vehicle Reg. No.: SLU5665X		Date of Loss: 30/03/2020 00:00 - :59 [27 Months and 23 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 7063584237SG		Policy/Cover Note No.: 1800040103							
Vehicle Reg. No. (Insured): SKN373U		Policy No. (Claimant):							
		Excess:							
Repairer: HARMONY MOTOR (JURONG) PTE LTD (HQ) 38 Toh Guan Road East, #01-53 Enterprise Hub, 608581 Jurong East - Tel: 65830001									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 13/04/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (02/04/2020): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents


























*SLU5665X (7063584237SG)
[SKN373U]

TP

Mar 30 2020 12:00AM

[ONG BEE CHOO]

HARMONY MOTOR (JURONG) PTE LTD

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
2	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
3	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
4	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
5	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
6	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
7	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
8	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
9	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
10	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
11	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
12	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
13	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
14	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
15	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
16	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
17	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
18	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
19	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
20	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
21	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
22	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
23	02/04/20 11:21	Front View	 Load JPG	<input checked="" type="checkbox"/>
24	02/04/20 11:22	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
25	02/04/20 11:22	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20004778/GTD3E2
Date: 03/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800040103
 Claimant Vehicle No: SLU5665X Insured Vehicle No: SKN373U
 Date of Loss: 30/03/2020 Nature of Claim: TP Claim No: 7063584237SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU5665X Engine No: P520485652
 Make & Model: MAZDA 3, 1.5 SEDAN (A) Chassis No: JM6BN22A8J0193628
 Reg. Date: 07/12/2017 (Man. Year: 2017) Odometer: 39772 km
 Colour: Grey
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 01/04/2020
 Date Inspected: 01/04/2020 Inspected At: 48 TOH GUAN ROAD EAST#02-113
 Repairer: HARMONY MOTOR (JURONG)
 PTE LTD (HQ)
 Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER TOW COVER	Missing	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
F=Franchise part.				Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >