



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20004814/Uqd3n2

73 BRAS BASAH ROAD

Date: 13-04-2020

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556



ATTN: JULIANA LEE

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKD 7887K	Veh. Inspected	SKF 2517B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1090349-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	02/04/2020

#### 2. Vehicle Particulars & Condition

Make & Model	AUDI A6 (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WAUZZZ4G6JN034633	Colour	GREY
Odometer	26863 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	MICHELIN	6 mm
L/H Front Tyre	225/55 R17	MICHELIN	6 mm
R/H Rear Tyre	225/55 R17	MICHELIN	6 mm
L/H Rear Tyre	225/55 R17	MICHELIN	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.
---

#### 5. General Information

Accident Date	30/03/2020	Inspect Date / Time	02/04/2020 ( 02:43 PM )
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------