



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20004874/Ftf3e2			
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			
		Date: 13-04-2020	
		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLM 9099X	Veh. Inspected	SHA 4047P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1090410-002	Excess (\$)	0.00
Assign From		Assign Date	02/04/2020
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVKU165021	Colour	BLUE
Odometer	77647	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	DAVANTI	7 mm
L/H Front Tyre	195/65 R15	DAVANTI	7 mm
R/H Rear Tyre	195/65 R15	DAVANTI	7 mm
L/H Rear Tyre	195/65 R15	DAVANTI	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/03/2020	Inspection Date	02/04/2020
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	