



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS3/AGI19016730/Gqf3e2-1

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 27-04-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKD 6362P	Veh. Inspected	SLP 5232M
Policy No.		Coverage (\$)	0.00
Claim No.	C10004081/KY	Excess (\$)	0.00
Assign From	JUSTIN WONG	Assign Date	02/04/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C 200	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WDD2040482A516012	Colour	WHITE
Odometer	132824	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45Z R17	MICHELIN	6 mm
L/H Front Tyre	225/45Z R17	MICHELIN	6 mm
R/H Rear Tyre	225/45Z R17	MICHELIN	6 mm
L/H Rear Tyre	225/45Z R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	20/09/2019	Inspection Date	24/09/2019
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------