22/03/2002 - ASS. REC. BY:	REF: (S/LP(>	004907/F)	rf3 Specia	al Instruction:	
Surveyor: Ram	ASSIGNM	ENT (Office)			
From (Person): Ong U U	of L			ate/Time: 3.4.77 3.58	pm
Estimated Cost:		Bill to:			
OD/TP/WS/TP RES/OD R To inspect Vehicle No:	es/eva/inv/mv/ SJk 4/8C	CS	Insured:	SKE 72883	
at Workshop m/s My (ar	consul tant			8 330006 0	
of 53 Paya Ubi Indush	ral park #01-3	3			
Policy No:		Claim No:	100/00	20/1905/0328	4
Sum Insured:		Excess:			
Make of Veh:			. D	O.A. 2.4.2020	
CA / REV / REP. / REV 24 Date/Time: 3/4/27 4-12/		Gric		H.O.D. Endorsement:	
Date/Time Action/Instruction	n (V) Estimut	to .			
	- My / = Why >0004		noA - 1	M 04 200	
SKE 7188	J-MI RUD DIN	4847/24	hon-	-04041 mm	
	1 3 1 1 2			7,71,70.0	
					× **
					4
CONTRACTOR OF THE CONTRACTOR O					

From: Date:	Veh No: SJK 418C Yr Regn: 02/10/2008
Estimated Cost:	Type: (I.Car) M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SJK 418 C	Make: Toyota altis c.c 1598
at Workshop m/s MY CAR CONSUTTANT	Colour Shoet A/C: Insured / Std / NI / NA
of 51 Vbi	Sp.Reading 17262 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: MROSSZEE106114988"
Claims No.	Gen. Cond: Good (Fair / Poor / Burnt
Sum Insured: Excess:	Steering Inorder Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil (/ S/Rim) STD A/Rim or
	Tyre Size: F: 195(65 R15
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA GY FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	точо / чоко ог
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. S mm R/Bal. S mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. S mm L/Bal. S mm
Est. Repairs: days Res.: Yes or No	D.O.A. 02/04/2020 D.O.I. 03/04/2020
Lum Sum: % 3 Val.: Yes tor No	Survey held at My car constant
CA / REV / REP. / 24 HRS	Des. of Damages : Fri Rear) O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	•
Range: \$5000-\$6000	
Repairdays : 3 repairdeys	(NS)
US \$3000 = (Red \$3816	-54 55%)
	1/000
MV:\$22695	
PV: \$11.265	
NV:\$11430/=	
Date/Time, File Pass to? : Prell. Report Da	ys Of Repair: 2
	survey No. of Trip: 3 - Survey Fee:
Date/Time, File Return to?	Transportation:
28 5 20 Typist Add Fee:	: Site Insp (\$)_s + R8_si
	: Interview (\$) Photos
eport Format :	Tech. (nys (\$) Others
for 200 / LE LE # \$3000 E	: Weetend 48 i
	TOTAL

Summer Lee (LKK Auto)

From:

ONG LI LI < llong@lonpac.com>

Sent:

Friday, 3 April, 2020 3:58 PM

To:

admin@mycar.sg; assignments@lkkauto.com; Summer Lee (LKK Auto)

Cc:

MT_Claim_SG

Subject:

RE: OUR REF: SJK418C YOUR REF: SKE7288J PRE-REPAIR INSPECTION FOR SJK418C

Our Ref: 20/20/20/VP05/023284 [External General]

Attachments:

SJK418C_02042020.pdf

Lonpac External - General

Dear Nivitha

Please arrange TP survey.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd 300 Beach Road #17-04/07 The Concourse

Singapore 199555

Tel: (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: My Car Consultant [mailto:admin@mycar.sg]

Sent: Friday, 3 April 2020 3:48 PM

To: ONG LI LI < llong@lonpac.com>; Quantum Risk < Info@quantum-risk.com.sg>; Ong Soo Ching

<ong.sooching@quantum-risk.com.sg>
Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: OUR REF: SJK418C YOUR REF: SKE7288J PRE-REPAIR INSPECTION FOR SJK418C Our Ref:

20/20/VP05/023284 [External General]

Without Prejudice

Dear All,

Please ignore previous email. Please help to assign LKK for survey.

Thanks & Regards,

Sylvia Chee

Tel: 83300060 Fax: 69255219

My Car Consultant Pte Ltd

53 Paya Ubi Industrial Park #01-33 S(408934)

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Fax Number Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

		ACCIDENT STATEMENT
	Date Of Report	02/04/2020 17:45
	Date Of Accident	02/04/2020 10:40
	Exact Location Of Accident	PIE TWDS JURONG WEST AVE 2
	Country/State of Loss	SINGAPORE
		DETAILS OF OWN VEHICLE
- 8	Vehicle Registration Number	SJK418C
	Insured/Policyholder	
	Name Of Registered Owner	KOH LEE CHING
	NRIC No	SXXXX967G
	Email Address	NOEMAIL
	Mobile Phone No	(LOCAL) +65-91010128
	Alternative Phone No	OFFICE-91010128
	Vehicle Particulars	
	Manufacturer	TOYOTA
j	Model	COROLLA ALTIS 1.6 AUTO
i	Exact Purpose for which vehicle was being used at ime of accident	PRIVATE USE
f	Are you claiming under your own insurance policy or repair to your vehicle?	NO
Į	f No, Please state action to be taken	THIRD PARTY
1	/ehicle Category	PRIVATE CAR
	nsurance Company	
١	lame of Insurance Company	FWD SINGAPORE PTE. LTD.
7	ype Of Coverage	COMPREHENSIVE
F	leet Policy	NO
F	Policy Number	PNPV2019-00005923
C	over Note Number	
E	Oriver	
Ν	ame of Driver	ANG TECK HOE
Ν	RIC No	SXXXX671F
D	ate Of Birth	26/06/1959
O	ccupation	OUTDOOR
D	ate Of Driving Pass	14/07/1979
D	riving Experience	40 YEARS AND 8 MONTHS
G	ender	MALE
M	obile Number	(LOCAL) +65-91010128
	SOURCE BY THE PROPERTY OF SOURCE	

OFFICE-91010128

NOEMAIL

Address

BLK 118 EDGEFIELD PLAINS

#14-306

Postcode

820118

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

NO 2

involved in the accident

YES

Was any body injured in the Accident? Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance. Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: -

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY

Police Station Address

ROAD: 10 UBI AVENUE 3, POSTCODE: 408865, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 65470000 - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20200402/7006.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKE7288J

Vehicle Make/Model/Colour

TOYOTA HARRIER

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

	DETAILS OF INJURED PERSON 1	
Name	ANG TECK HOE	40
Approximate Age		
Injuries Sustain	BODY	
Injured person in which vehicle?	SJK418C	
Were seat belts worn?	YES	
Was this injured conveyed to hospital by ambulance?	NO	
Address		
Postcode		

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- I. Please report correctly the details of the accident to speed up the claims process
- I This form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>republishe policy liability</u>.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any faire reporting may be referred to the Police for investigation.
- 5. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 5. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be toilectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me,
 which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the
 external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Furposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Oriver's Signature (If driver is not the policyholder)

Cate & Time:

Reporting Centre Personnel's Senature

Name:

NRIC/FIN No.:

SALARIE CEMENTALISM WHEN THE

Accident Sketch Plan

Refer to police report.	
DESCRIBE CIRCUMSTANCES OF THE ACCIDENT	A SIKAI8C 8 CLENCE]

Sale L

Page 5 of 20

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	967G
Vehicle No.:	SJK418C
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Apr 2020
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4786361
Chassis No.:	MR053ZEE106114988
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,777.00
Original Registration Date:	02 Oct 2008
First Registration Date:	02 Oct 2008
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$16,777.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	30 Sep 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$16,170.00
COE Rebate Amount:	\$11,265.00
Total Rebate Amount: Message	\$11,265.00
Please note that the 5-year COE for this vehicle cannot be f	further renewed. The vehicle must be de-registered upon COE expiry or when the

vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Apr 2020

3

Rawaing: 3 years Smarths 28 dys (41.9) OK Degri: \$6500/yearly \$541.66/monthy 41.9x\$541.66 = \$22695.55

SGCARMART.COM

Login Sign up

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Best Car Repair Workshops in Singapore

Browse more than 3,000 car workshops in Singapore. You can read customers' reviews & ratings on their services too.

Toyota altis Price Range ▼ Depreciation ▼ > 10 year(! ▼ Vehicle Type ▼ Madvanced Search

Home » Used Cars » ES Automobile Pte Ltd » Toyota Corolla Altis 1.6A (COE till 04/2023)

Toyota Corolla Altis 1.6A (COE till 04/2023)

Overview	Financial	Insurance	Accessories	Similar	Research	Photos
Price	\$19,800					
Depreciation 💮	\$6,550 /y	ır	Reg Date		16-Apr-2008 (3yrs 9days COE left)	
Mileage	99,000 kr	m (8.3k /yr)	Manufact	tured 🕝	2008	
Road Tax	\$890 /yr		Transmis	sion	Auto	
Dereg Value	\$11,692	as of today (chang	ge) OMV		\$16,994	
COE ()	\$19,328		ARF		\$16,994	
Engine Cap	1,598 cc		Power		80.0 kW (107 bhp)	
Curb Weight	1,195 kg		No. of Ov	vners 🦪	2	
Type of Vehicle	Mid-Sized	l Sedan				
Features						
Original Condition.	View specs of	the Toyota Coroll	ia Altis (2008-2013)		

Accessories

Factory Fitted Interior.

Description

1St 10 Years Maintain By Agent (Borneo Motors) Extremely Low Mileage Unit! Vehicle Well Maintained By Ex-Owner. No Repairs Needed. Full Loan Available At Flexible Interest Rate. Purchase Comes With New Paintwork, 6 Months Warranty And A Complimentary Servicing Package. STA/Vicom Evaluation Friendly. Bank And In House Loan Supported. Viewing Available Daily By Appointment.

Category

COE Car, Premium Ad Car, Low Mileage Car

Status

Available

Resources



Car Valuation - Free


Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 05-Apr-2020 | Last Updated on: 05-Apr-2020











19.7K Apr-08 Apr-08 Reg Date

Click on the point to view the vehicle

Compare Add note

More Actions

Seller Information

Shortlist

Report Error

ES Automobile Pte Ltd

6 vehicles for sale. 27 sold in past 3 mths

8 Kaki Bukit Avenue 4 #03-52 Premier @ Kaki Bukit Search cars nearby May-08

MYCAR

MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date:

3/4/2020

Vehicle:

SJK418C

Make / Model:

TOYOTA ALTIS

Chassis:

MR053ZEE106114988

		ISSIS:		IVIRU53ZE	EIU	0114900	<u>ee</u>
No.	Description	Unit	U	nit Price		Amount	
	Parts Replacement:						
1	REAR BUMPER DEF	1	\$	527.90	\$	527.90	
2	REAR BUMPER SIDE RETAINER LHXM	1	\$	45.30	\$	45.30	
3	REAR BUMPER BRACKET LH 🥻 NEC	1-	\$	29.80	\$	29.80	1
4	REAR BUMPER REFLECTOR LH	1	\$	43.60	\$	43.60	/.
5	REAR TAILLAMP LH BY	1	\$	696.50	\$	696.50	\$330
6	REAR TAILLAMP INNER PANEL LH	1	\$	559.50	\$	559.50	
7	REAR TAILLAMP LOWER BRACKET LH	1	\$	89.60	\$	89.60	
8	REAR TAILLAMP CLIPS nec	2	\$	4.50	\$	9.00	/.
9	REAR BOOTLID BUC	1	\$	845.30	\$	846.30	
10	REAR BOOTLID LOCK	1	\$	109.40	\$	109.40	\$65
11	REAR BOOTLID LOCK CATCH XUP	_1	\$	53.40	\$	53.40	
12	REAR BOOTLID LAMP Ser fut	1	\$	441.80	\$	441.80	\$230
13	REAR BOOTLID EMBLEM LOGO ne(1	\$	42.20	\$	42.20	
14	REAR BOOTLID EMBLEM COROLLANCE	1	\$	33.30	\$	33.30	
15	REAR BOOTLID EMBLEM ALTIS NEC	1	\$	24.85	\$	24.85	- .
16	REAR BOOT WEATHER STRIPE 🏺 OEF	1	\$	145.40	\$	145.40	
17	REAR END PANEL 🦋 🕊 🤾	1	\$	708.30	\$	708.30	X
18	REAR END PANEL TOP GARNISH FOR	1	\$	86.30	\$	86.30	148-70/
19	REAR FENDER LH	1	\$	889.60	\$	889.60	
					\$	5,382.05	1
			Le	ess 25%	\$	1,345.51	İ
				Total	\$	4,036.54	İ
	S/Nett items:		8				1
1	REAR REVERSE SENSOR 4 5C	1 SET	\$	250.00	\$	250.00	\$200
2	REAR BUMPER CLIP NEC	1 SET	\$	80.00	\$	80.00	
3	REAR END PANEL GARNISH CLIP 🕏 NEC	1 SET	\$	30.00	\$	30.00	
4	FLOOR PANEL SEALANT 👢 🗙 🗥	1	\$	50.00	\$	50.00	×
5	END PANEL SEALANT WEC	1	\$	50.00	\$	50.00	
		Seesally and	1172		\$	460.00	
		3					I

		Parts Rep Total Am	ount	for I		\$ 4,496.54 2,320.00 6,816.54	
					•	\$ 2,320.00	1
6	PANEL BEATING ON AFFECTED AREAS		1	\$	1,000.00	\$ 1,000.00	\$6
5	SPRAY PAINTING ON AFFECTED AREAS	5	1	\$	800.00	\$ 800.00	\$60
4	APPLY ANTI RUST ON AFFECTED AREAS	S	1	\$	200.00	\$ 200.00	\$5
3	TO RESPRAY UNDERCOATING		1	\$	120.00	\$ 120.00	€8€
2	TO REMOVE AND REFIT REVERSE SENSO	OR .	1	\$	150.00	\$ 150.00	\$8
1	TO CHECK ELECTRICAL WIRING		1	\$	50.00	\$ 50.00	
	Labour to:				Description of the second		1

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer Signature:

Date:

Ran (LKC)

3/4/2020 (645

Bareguran Dixiranto con

Pareguran Dixiranto

8867277 Pareguranto

43-19an Jays

43-19an Jays