

ASS. REP. BY: REF: 31036 2020 427 / HFB-1 Special Instruction:

Number

From (Person): Subramaniam Dingasani of MLG Date/Time: 20.1.2020 1.50p m

From (Plant): ASSIGNMENT (Office) Bill to:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PB A 991K Insured: SGZ 7923X

at Workshop m/s: O.M motor Service Tel: 87990940 - Johor

of: 10 KALC Bukit Road 2 #0136

Policy No: _____ Claim No: 709622755259

Sum Insured: _____ Excess: _____

Make of Veh: _____ DOA: 13.1.2020

(Client's Record) CA / REV / REP. / RBV 24 HRS: map 21. Jan. 2020

Date/Time: 20.1.2020 1.50p m Person Contacted: MS Lim H.O.D Endorsement: _____

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) (Initial)
	4 days
21/1/20	→ survey taken
31/1/20	→ Repair taken
1/2	→ other party working with

Submit lump sum \$3100+ , (Red 4026; 56%)