



PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers
Blk 779 #01-1545 Yishun Ave 2 Singapore 760779
Tel: 62934822 Fax: 62963283
E-mail: admin@priorityservices.sg

Your Ref. : SKL9752K/Steve
Our Ref. : TP-0122/03/18

Date : 2 April 2018

M/s. ERGO Insurance Pte Ltd
5 Temasek Boulevard #04-01
Suntec Tower Five
Singapore 038985

Attn. : Mr. Steve Lim

Dear Sir,

Pre-Repair Survey
Vehicle No.: SLT 7462 G
Date Of Accident: 10-Mar-2018

Date and Time of Request : 13-Mar-2018 / 9.33am

Date and Time of Inspection : 1) 20-Mar-2018 / 11.15am (PRI by appointment)
2) 27-Mar-2018 / 10.20am (For dismantled items)
3) 29-Mar-2018 / 9.30am (For after repair)
@ M/s. Precise Auto Service

Particulars of Vehicle

Registration No.	: SLT 7462 G
Make / Model	: Ssangyong / Tivoli (A)
Year	: 2017
Colour	: Met. Black
Odometer	: 9013 km
Engine Capacity	: 1597 cc
Carrying Capacity	: 4
Engine No.	: -
Chassis / Body Frame	: KPT30B1VSHPI76946
Radio / CD Player	: Yes
Air-Con Conditioner	: Yes
Other Apparent Accessories	: No
Spare Tyre	: No
Jack / Tools	: Intact

(59) Photographs of vehicle taken.

Documents Available At Time Of Inspection

1) Singapore Accident Statement (SAS)

Visual Damages

At the rear portion

Damages subject to consistency.

Remarks

Despite our request, the repairer would not provide:-

1) Repairer estimate

Recommendation of repairs attached.

Yours Very Truly
PRIORITY SERVICES



LAWRENCE NG
Motor Appraiser

Registration No.	: SLT 7462 G
Make / Model	: Ssangyong / Tivoli (A)
Year	: 2017
Chassis	: KPT30B1VSHPI76946

Estimated repair cost for damages found during first inspection on.

QTY	SPARE PARTS	ESTIMATED PART PRICE
1	REAR BUMPER	\$ 385.40
1	REAR BUMPER CLIPS	40.00
1	REAR BUMPER LH LOWER BRACKET	13.50
1	REAR BUMPER REINFORCEMENT	287.80
1	REAR BUMPER REINFORCEMENT LH BRACKET	64.30
1	REAR BUMPER LH SIDE PROTECTOR	63.69
1	REAR BUMPER LH SIDE PROTECTOR REFLECTOR	17.20
1		
		=====
		\$ 871.89
	Less 10%:-	87.19
		=====
	Total For Parts:-	\$ 784.70
		=====

LABOUR CHARGES:

Labour charges.	\$ 500.00
Spray painting.	600.00
	=====
Grand Total:	\$ 1884.70
	=====

Proposed Lumpsum repairs	: \$1500.00
Estimated period of repairs	: 3 working days
Pre-accident market value	: \$120,000.00
PARF/COE rebate	: \$ 53,370.00
Economical limit repair	: \$ 66,600.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/03/2018 10:24
Date Of Accident	10/03/2018 13:00
Exact Location Of Accident	WHAMPOA FLYOVER TWDS CHANGI (PIE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT7462G
Insured/Policyholder	
Name Of Registered Owner	AUTOMOBIL LEASING PTE LTD
Co Reg No	200701438D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64682200
Vehicle Particulars	
Manufacturer	SSANGYONG
Model	TIVOLI-1.6 G 6AT ABS 2WD (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	MU011879
Cover Note Number	
Driver	
Name of Driver	LEE KENG HENG
NRIC No	S8619245D
Date Of Birth	14/07/1986
Occupation	INDOOR
Date Of Driving Pass	08/04/2009
Driving Experience	8 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96953553
Fax Number	
Contact Number	OFFICE-96953553
Email Address	LEEJAKE86@GMAIL.COM

Address	BLK 525 HOUGANG AVE 6 #03-177
Postcode	530525
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SKL9752K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan



Describe Circumstances of the Accident

My Vehicle (A) was travelling along Whampoa Flyover towards
P1B Changi.
My front vehicle stopped so I stopped also. After a second, vehicle
(B) from behind hit into my vehicle (A).

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

12/03/18 840am



SsangYong Motor Co., Ltd.			
KPT30B1VSHP176946			
GROSS VEHICLE WEIGHT RATING	1810		KG
GROSS VEHICLE WEIGHT TRAILER WITH BRAKE	2810		KG
FRONT AXLE MAX WEIGHT RATING	1060		KG
REAR AXLE MAX WEIGHT RATING	1160		KG
BODY PAINT COLOR	LAK		
DATE OF MANUFACTURE			





























RESURVEYED
AFTER REPAIRS







