

ASS. REC. BY: Ram

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHA 4181 J Yr Regn: 20/12/2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai i40 C.C. 1685Colour: blue A/C: Insured / Std / NI / NASp. Reading: 338179 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KAMHLBAUMH099956Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 02/04/2020 D.O.I. 3/4/2020Survey held at comfidelgro (Layan)Des. of Damages: Frnt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

EQ

P/P

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.E.H. (\$ _____)

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

EQ Insurance Company Ltd (HQ)

Singapore

L.Ke EQ NS

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	02/04/2020
Vehicle Reg. No.:	SHA4181J	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	20/12/2017
Vehicle Colour:	BLUE		
Engine No:	D4FDGU706206	Chassis No:	KMHLB41UMHU099956
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	2,750.08
Miscellaneous Items	0.00
Labour	1,230.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,980.08
+ GST 7.00% (S\$)	278.61
Nett Amount (S\$)	4,258.69

This claim is handled by: LIM KWOK ENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

EQ Insurance Company Ltd (HQ)

Singapore

Lke EQ NS

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	02/04/2020
Vehicle Reg. No.:	SHA4181J	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	20/12/2017
Vehicle Colour:	BLUE		
Engine No:	D4FDGU706206	Chassis No:	KMHLB41UMHU099956
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	2,750.08
Miscellaneous Items	0.00
Labour	1,230.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,980.08
+ GST 7.00% (S\$)	278.61
Nett Amount (S\$)	4,258.69

This claim is handled by: LIM KWOK ENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 02 Apr 2020)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA4181J/02/04/2020 18:14**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER COVER DEF ✓	20.00	0.00	*1,052.20 FL
2	1		*FRT BUMPER TOP BRACKET RH ?	20.00	0.00	*22.40 FL
3	1		*FRT BUMPER SIDE BRACKET RH xxx Incc ✓	20.00	0.00	*24.60 FL
4	1		*HEADLAMP ASSY RH scr ✓	20.00	0.00	*1,388.00 FL
5	1		*FRT FENDER RH BUC ✓	20.00	0.00	*663.00 FL
6	1		*FRT FENDER SHIELD RH Cut ✓	20.00	0.00	*174.90 FL
7	1		*FRT WHEEL HUB CAP RH scr ✓	20.00	0.00	*112.50 FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	3,437.60
- List Item Discount on L Items (\$\$)	687.52
Total Parts (\$\$)	2,750.08

ComfortDelGro Engineering Pte Ltd/SHA4181J/02/04/2020 18:14. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	600.00 \$560
2	SPRAY PAINTING CHARGE	New	450.00 \$400
3	WIRING CHARGE	New	50.00 ✓
4	TUFF KOTE	New	50.00 \$30
5	FRT WHEEL ALIGNMENT	New	80.00 xun
Gross Labour Cost (\$\$)			1,230.00

ComfortDelGro Engineering Pte Ltd/SHA4181J/02/04/2020 18:14. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

Ram (LKK)
 3/4/2020 1505
 Ram (LKK) @lkkauto.com
 28622728
 (P/O)
 Beffaint photo