



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

SIM MONG HONG
BLK 322B ANCHORVALE DRIVE #15-138
SINGAPORE 542322

Attention : THE OWNER
Contact : 93838648

Not Authorized
11 Sep @ 3950h
Resurvey After Rain
4 days

Estimate : ES006981

Date : 06/04/2020
Vehicle Num. : SLD7520G
Make/Model : TOYOTA ALTIS 1.6-2016
Chassis/Eng# : MR053REH104552891/1ZRX580006
Accident Date : 06/04/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	FRONT DOOR L/H		
2.	2	FRONT DOOR BLACK STICKER L/H		
3.	1	REAR DOOR L/H		
4.	2	REAR DOOR BLACK STICKER L/H		
5.	1	REAR FENDER L/H		
6.	1	REAR W/SCREEN MOULDING		
7.	1	REAR SPORT RIM L/H		
8.	1	REAR WHEEL BEARING L/H		
9.	1	REAR SHOCK ABSORBER L/H		
List TotalS\$:				6,423.51
20.00% Discount S\$:				1,284.70
25%				5,138.81
SPECIAL NETT ITEMS :				
1.	1	REAR W/SCREEN SEALANT		65.00
Special Nett Total S\$:				65.00
LABOUR :				
REMOVE & REINSTALL REAR W/SCREEN GLASS				180.00
TRANSFER L/H FRONT DOOR COMPONENTS TO NEW DOOR				150.00
TRANSFER L/H REAR DOOR COMPONENTS TO NEW DOOR				150.00
RUST PROOFING TREATMENT				100.00
SPRAY PAINT DAMAGED AREA AFFECTED				980.00
REMOVE & REINSTALL REAR SUSPENSION L/H				250.00
COMPUTER WHEEL ALIGNMENT				120.00
TO CUT OFF L/H REAR FENDER AND CHANGE ALL NECESSARY				

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

SIM MONG HONG
BLK 322B ANCHORVALE DRIVE #15-138
SINGAPORE 542322

Attention : THE OWNER
Contact : 93838648

Estimate : ES006981

Date : 06/04/2020
Vehicle Num. : SLD7520G
Make/Model : TOYOTA ALTIS 1.6-2016
Chassis/Eng# : MR053REH104552891/1ZRX580006
Accident Date : 06/04/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		PARTS		1,100.00
		Labour Total S\$:		3,030.00

SingDollars : Eight Thousand Two Hundred Thirty-Three & Cents Eighty-One Only

Total S\$: 8,233.81
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun