ASS. REC. BY: Tayfun | REF: III

ASSIGNMENT

From: _____ Date: _____

Estimated Cost. _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $18K.

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKS 8867Y Yr Regn: 2011, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Honda City c.c 1497

Colour Gold A/C: Insured / Std / NI / NA

Sp.Reading 190984 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRHGM26509PD20550

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 175/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or _____

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	7/4/20

Survey held at Chery Auto.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Soon Lee st #06-97

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Preli. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ : Tech. Invs ($ _____)

Survey Fee:

Transportation: __S + RS__SI

Photos

Others

Report Format : _____

CHENG AUTO
Bodyworks
GST Reg No M90372111L

Reporting Centre 5 Soon Lee Street, #01-60 Pioneer Point, Singapore 627607
Workshop 5 Soon Lee Street, #01-62 Pioneer Point, Singapore 627607
Spray-painting 1 Soon Lee Street, #06-41 Pioneer Centre, Singapore 627605

Office: 6631 0707 Fax: 6316 2411 cab@chengauto.com Cheng Auto Bodyworks Singapore

CHENG AUTO
86667775

DATE : 6/4/2020

REPAIR DETAILS

REFERENCE

Vehicle Reg No.	: SKB8867Y	
Make & Model	: HONDA / CITY 1.5L I-VTEC AUTO	
Chassis No.	: MRHGM26509P020550	
Engine No.	: L15A71811762	
Manufactured Year	: 2009	
Labour	: **REPAIRER'S**	
TP Vehicle Reg No.	: SHC2271K	
DOA & Location	: 01/04/2020	UPPER SERANGOON ROAD TO PIE (TUAS) JUNCTION
Our Ref	: SKB8867Y	/ VASU BABU

ESTIMATES OF PARTS

No.	Qty	Description	Part No.		Price
1	1	FRT BUMPER		$	559.80
2	1	FRT BUMPER RETAINER LH		$	37.50
3	1	FRT BUMPER RETAINER RH		$	37.50
4	1	RADIATOR GRILLE ASSY		$	356.40
5	1	GRILLE LOGO		$	28.32
6	1	HEADLAMP LH		$	428.15
7	1	HEADLAMP RH		$	428.15
8	1	REINFORCEMENT		$	253.10
9	1	CONDENSAR ASSY		$	650.80
10	1	FRONT SUPPORT PANEL		$	458.20
11	1	FENDER RH		$	395.20

Sub-Total (S$)	$	3,633.12
SAAA List Item Discount 20% (S$)	$	726.62
Sub-Total (S$)	$	2,906.50

LABOUR

No.	Description		Price
1	LABOUR	$	1,200.00
2	SPRAYPAINTING	$	600.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	$	150.00

Total Labour (S$)	$	1,950.00

MISCELLANEOUS ITEMS

No.	Description		Price
1	NO. PLATE W/ COVER	$	100.00
2	AIRCON GAS	$	45.00
3	COOLANT	$	100.00

Total Miscellaneous Items (S$)	$	245.00

Total Parts	**(S$)**	$	2,906.50
Total Labour	**(S$)**	$	1,950.00
Total Miscellaneous	**(S$)**	$	245.00
Sub-Total	**(S$)**	$	5,101.50
GST 7%	**(S$)**	$	357.10
Grand Total	**(S$)**	$	5,458.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjiah 97499749
- WP'
7/4/20 @ 4.30pm
Lumpsum
Resurvey after repair -
tanjiah @ hotmail.com
04 days