

ASS. REC. BY:

REF: AG / 20005033/Kg

C

Kenneth

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s Optima

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 1.8.1 days Res.: Yes or No

Lum Sum: 04 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: PKK 1177B Yr Regn: 06.16

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Honda <sup>SA</sup> vecc c.c. 1496

Colour: M. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 148087 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RU3 1204460

Gen. Cond:  Good /  Fair /  Poor /  Burnt

Steering:  In order /  Jammed /  Leaked /  Burnt or

Brake:  In order /  Jammed /  Leaked /  Burnt or

Modl:  Nil /  S/Rlm /  STD /  Rlm or

Tyre Size: F: 215/60R16

R: \_\_\_\_\_

BS /  DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 2 mm

Rear

R/Bal. 2 mm

L/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 3/13/20

D.O.I. 9/4/2020

Survey held at \_\_\_\_\_

Des. of Damages:  Frt /  Rear /  O/S /  N/S /  U/C /  Rooftop or

O/S Frt  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

9/7 @ 1607.04 Confirmed

Date/Time, File Pass to?

: Prell. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation: \_\_\_\_\_  
S + RS. \$ \_\_\_\_\_

Fuel \$ \_\_\_\_\_

Others \$ \_\_\_\_\_

TOTAL

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Date: 06.04.2020  
Vehicle No: SGK1177B  
Model: HONDA VEZEL 1.5X HYBRID  
Chassis: RU31204460-2016  
Reg.Year: 2016

Third Party Insurer: AIG  
Third Party Veh No: SDU8908X  
Date of Accident: 31.03.2020

*Not Notified*  
*Running B4 pain 4 days*

### ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT FENDER RH	1		<i>Pr</i> \$405.20
2	FRONT FENDER 'HYBRID 'EMBLEM RH	1		<i>na</i> \$68.50
3	FRONT FENDER INNER LINER CLIPS	8	\$5.50	<i>na</i> \$44.00
4	FRONT FENDER EXTENTION COVER RH	1		<i>Paint</i> \$172.10
5	FRONT BUMPER SIDE BRACKET RH	1		<i>Pr</i> \$29.50
6	FRONT DOOR RH	1		<i>R</i> \$936.40
7	FRONT BUMPER CLIPS	8	\$5.50	<i>na</i> \$44.00
8	FRONT BUMPER	1		REPAIR
SUB TOTAL				\$1,699.70
LESS 20%				-\$339.94
PARTS TOTAL				\$1,359.76

#### LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPAIR, REPLACE, REFIX & READJUST FRONT ACCIDENT AREAS & ETC. *400* \$480.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH. *na* \$120.00 *X*

LABOUR CHARGES TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC. *na* \$60.00 *X*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER RH & FRONT DOOR RH. *680* \$750.00

LABOUR TOTAL \$1,410.00

TOTAL \$2,769.76

TingAn

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

#### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

#### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

#### Branch

551 Upper Thomson Road Singapore 574415  
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	607E
Vehicle Details	
Vehicle No.:	SGK1177B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Apr 2020
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X HYBRID CVT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	LEB5904470
Chassis No.:	RU31204460
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$24,440.00
Original Registration Date:	16 Jun 2016
First Registration Date:	16 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jun 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jun 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,000.00
COE Rebate Amount:	\$34,704.00
<b>Total Rebate Amount:</b>	<b>\$38,454.00</b>

The information contained herein is correct as at 04 Apr 2020

OK