

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305392292

Date : 13/04/20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : TAUFIKH

Vehicle Reg No. : SHC2454A

Date of Accident : 05-Apr-20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SBR 989D

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,081.62

(b) Labour Charges \$550.00

Total for Part-By-Part Repair Cost \$1,631.62

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature

Name : TAUFIKH

Date :

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	-----			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 13.04.2020

REPAIR ESTIMATE

Time: 13:56:23

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305392292
REGN NO : SHC2454A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 10.07.2019
DATE/TIME IN : 05.04.2020 13:10
ACCIDENT DATE : 05.04.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52
0002 04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00
0003 04-01-0104-2545-G	REAR BUMPER LWR MOULDING	1	155.00	20.00	124.00
0004 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60
0005 09-01-9999-0068-A	REVERSE SENSOR	1	180.00	10.00	162.00
0006 FNPS	NO PLATE(S)W/TRIM COVER	1 N	55.00	10.00	49.50

SUB-TOTAL : 1,081.62

JOB NATURE

0000 PB	PANEL BEATING	320.00
0001 SP	SPRAYPAINT CHARGE	200.00
0002 L	R/I REVERSE SENSOR	30.00
0003 23-01	TOWING FEE	0.00

SUB-TOTAL : 550.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 13.04.2020

REPAIR ESTIMATE

Time: 13:56:23

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305392292
REGN NO : SHC2454A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 10.07.2019
DATE/TIME IN : 05.04.2020 13:10
ACCIDENT DATE : 05.04.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,631.62


MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :