



## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE NTUC-45  
LKK-Ram

(CSAT)

Date: 04.04.2020

Time: 10:02:42

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305392007  
REGN NO : SHA8277R  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 25.08.2016  
DATE/TIME IN : 03.04.2020 16:00  
ACCIDENT DATE : 03.04.2020

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

|                        |                        |   |          |       |        |     |
|------------------------|------------------------|---|----------|-------|--------|-----|
| 0001 04-01-0103-2322-A | FRT BUMPER             | 1 | 1,052.20 | 20.00 | 841.76 | Rp  |
| 0002 04-01-0103-0637-G | FRT BUMPER UPR BRKT LH | 1 | 22.40    | 20.00 | 17.92  | X   |
| 0003 04-01-0103-0639-G | FRT BUMPER BRKT LH     | 1 | 24.60    | 20.00 | 19.68  | X   |
| 0004 04-01-0103-0574-A | FRT FENDER LH          | 1 | 663.00   | 20.00 | 530.40 | bt  |
| 0005 04-01-0103-0658-G | FRT WHEEL CAP LH       | 1 | 107.10   | 20.00 | 85.68  | ant |

SUB-TOTAL : 1,495.44

## JOB NATURE

|            |                              |        |     |
|------------|------------------------------|--------|-----|
| 0000 PB    | PANEL BEATING                | 300.00 | 280 |
| 0001 SP    | SPRAYPAINT-BONNET Etc        | 750.00 | 400 |
| 0002 20-00 | TUFF COAT ON AFFECTED PARTS. | 40.00  | 30  |
| 0003 20-05 | Frt Bumper Adv.Sticker.      | 100.00 | nt  |
| 0004 20-05 | Frt Fender Adv.Sticker LH    | 100.00 | nt  |

SUB-TOTAL : 1,290.00

COMFORT DEL GRO ENGINEERING PTE LTD

REPAIR ESTIMATE

(SAT)

Date: 04.04.2020

Time: 10:02:42

Page: 2

JS

NTUC-LFS

Lxx - Pam

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAR PTE LTD  
381 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305392007  
REGN NO : SHA8277R  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 25.08.2016  
DATE/TIME IN : 03.04.2020 16:0  
ACCIDENT DATE : 03.04.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,785.44

AUTHORISED : YES / NO

MVA NAME & SIGNATURE  
DATE :

SURVEYOR NAME & SIGNATURE  
DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjik 97495749

'WP'

6/4/20 @ 4pm

Lunysun

Resurvey after repair

03 days

sure@lkkauto.com

tanjik@lkkauto.com

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 119271  
 Mainline : 65 6383 6280 Facsimile : 65 6280 9755

Workshops:  
 59 Loyang Drive Singapore 505063 24 Senoko Loop Singapore 758156  
 103 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way Singapore 72879  
 15 Pandan Road Singapore 110186 1000 Upper Changi Road Singapore 487000  
 100 Upper Changi Road Singapore 487000

Date/Time: 04.04.2020 09:53 Page: 1

Member of COMFORTDELGRO

ARC Repair TP(CFSO)

## JOB CARD

Sales Order:

(Sat)

JC NO.: 30539200 /

CITYCAB PTE LTD  
 7010070  
 88.3 SIN MING DRIVE  
 Singapore SINGAPORE 575717  
 65551186

|                                 |                                |
|---------------------------------|--------------------------------|
| REGN NO.: SHA8277R              | MILEAGE                        |
| MAKE: HYUNDAI                   | FUEL                           |
| MODEL: I-40                     | DATE/TIME IN: 03.04.2020 16:00 |
| YR OF MANU.: 25.08.2016         | TARGET DATE                    |
| CHASSIS CODE: KMHLB41UMGU093531 | COMPLETION DATE/TIME           |

COUNT CARD NO.


Accident Date: 03.04.2020  
 NATURE: 3P 03.04.2020

JOB DESCRIPTION

NTUC - SJA 432 M

S/NO LABOR CODE DESCRIPTION

LKK - Ram



ISSUED & PASSED OUT BY

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Payment Slip

Exit Pass

SHA8277R

LIMITS

Vehicle No.:

SHA8277R

Service Advisor

Signature/Date

Name of Service Advisor

Date