

ASS. FILE BY

brl.


~~CS/III 20005078/Gqf3~~

ASSIGNMENT

From \_\_\_\_\_ Date \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD  TB / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s **T & S Motor**.  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: **\$48K**  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : **Yes** or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : **Yes** or No  
 Est. Repairs: **4** days Res.: **Yes** or No  
 Lum Sum: **20** % 3 Val.: **Yes** or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **SLC57926** (r Regn: **15 Sep 2009**)  
 Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: **Toyota wsh 1.8Xc 1797**  
 Colour: **silver** A/C: **Insured / Std / NI / NA**  
 Sp. Reading: **249866** T/Radio: **Insured / Std / NI / NA**  
 Eng/No: \_\_\_\_\_  
 C/No: **26E 200001461**  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: **NI** / S/Rim / STD  R/Rim or \_\_\_\_\_  
 Tyre Size: F: **205/55R16**  
 R: **11**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **CST**  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. **5** mm R/Bal. **5** mm  
 L/Bal. **5** mm L/Bal. **5** mm  
 D.O.A. \_\_\_\_\_ D.O.I. **08-04-20**  
 Survey held at **W/S** **3:30pm**  
 Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	col: 35780
08/4	Finalized \$1400 with Mei Hua. (Red: \$5678.40, 80%)

Date/Time, File Pass to?

1) 13/04 Typist

Date/Time, File Return to?

2)

: Prel. Report  
 : Final Report

Days Of Repair: **4**

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

3 + RS. SI

Date :08/04/2020

97629883 mes lma.

India International Insurance Pte Ltd  
 64 Cecil Street  
 #04/06-00 IOB Building  
 Singapore 049711

573.2

20% 1140

Re: Estimated repair cost of Toyota Wish SLC5792G accident on 07/04/2020  
 involved with SHD3135J.

1 pc	Tailgate	X repair		\$	1,272.40	
1 pc	Tailgate glass moulding	X NN		\$	180.00	
1 pc	Tailgate logo emblem	X		\$	72.90	
1 pc	Tailgate inner trim	X		\$	345.20	
1 pc	Tailgate lock	X		\$	470.40	
1 pc	Tailgate weatherstrip	X		\$	322.30	
1 pc	Rear bumper	X		\$	500.30	
2 pcs	Rear bumper reflector @ \$57.60	X		\$	115.20	
2 pcs	Rear bumper side retainer LH & RH @ \$60.80	X		\$	121.60	
2 pcs	Rear bumper impact bracket LH & RH @ \$89.80	X		\$	179.60	
1 pc	Rear end panel	X repair		\$	468.50	
1 pc	Tailgate glass sealant	X		\$	80.00	
1 pc	Tailgate glass inner seal	X		\$	40.00	
1 pc	Panel joint sealant	X		\$	60.00	
1 set	Tailgate inner trim clip	X		\$	60.00	
1 set	Rear bumper clips	X		\$	60.00	
1 set	Reverse sensor	X		\$	250.00	30 (SN)
				\$	4,578.40	200 (SN)
	Labour charge for remove, replace and refit accident dented parts and panel beat accident dented parts.			\$	900.00	400
	Labour to remove & refit rear trimmings, etc			\$	150.00	60
	Labour to replace & refit reverse sensor			\$	100.00	40
	Labour to replace & refit tailgate glass			\$	200.00	X NN
	Spray painting on accident affected areas.			\$	900.00	600
	To apply rustproof treatment to the replaced/repared parts.			\$	150.00	X NN
	To conduct wiring check			\$	100.00	X NN
	<b>TOTAL:</b>			<u>\$</u>	<u>7,078.40</u>	1100

4 Days.  
 Imp Sum repair.  
 After repair photos.  
 Guo Qiang - 82880282  
 08/4/2020.

1759.9  
 20% 1140

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: