





PRE-REPAIR INSPECTION REPORT				
LONPAC INSURANCE BHD		Ref: CS3/LPC20005089/Qqf3e2		
300 BEACH ROAD #17-04/07 THE CONCOURSE		Date: 24-04-2020		
SINGAPORE 199555		Code: LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLG 8767P	Veh. Inspected	SKL 1486G	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/20/20/VP05/023302	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	08/04/2020	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 528I A	c.c	2996	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WBAFS52080C276310	Colour	WHITE	
Odometer	185316 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R19	GOODYEAR	6 mm	
L/H Front Tyre	245/40 R19	GOODYEAR	6 mm	
R/H Rear Tyre	245/40 R19	GOODYEAR	6 mm	
L/H Rear Tyre	245/40 R19	GOODYEAR	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
5. General Information				
Accident Date	03/04/2020	Inspect Date / Time	16/04/2020 (01:53 PM)	
Survey held at	WAH YU AUTOMOTIVE BODY WORK 176 SIN MING DRIVE #05-09 SINGAPORE 575721			
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC20005089/Qqf3e2

Inspected By



OI SUN PIN

Asst. Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.