

22/03/2002

ASS. REC. BY:

REF:

CS3 / LPC 20005049 / Qqf3

Special Instruction:

Surveyor: Sun Pin

ASSIGNMENT (Office)

From (Person):

Ong Li Li

of

LPC

Date/Time:

8.4.20 4.00p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SK L 148LG

Insured:

SLG 8767P

at Workshop in/s

Wah Yn Automotive Body Work

Tel:

6455 2309 / 9736 0862

of

176 sin ming Drive #05-04

Policy No:

Claim No:

20/20/20 / VP05/023302

Sum Insured:

Excess:

Make of Veh:

D.O.A.

3.4.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

imp

H.O.D. Endorsement:

Date/Time:

8.4.20 4.00p.m

Person Contacted:

Mr Geo

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SLG 8767P - X

SK L 1486G - X

upload Done.

17/04/20

Submit PRS.