



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20005103/Uyf3e2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 22-04-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 2057G	Veh. Inspected	XD 5077R
Policy No.		Coverage (\$)	0.00
Claim No.	C10006110	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	09/04/2020

2. Vehicle Particulars & Condition

Make & Model	IVECO TRAKKER (M)	c.c	12882
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WJME2NSS40C233334	Colour	ORANGE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	AMBERSTONE	5 mm
L/H Front Tyre	295/80 R22.5	AMBERSTONE	5 mm
R/H Rear Tyre	275/70 R22.5 (D/D)	AMBERSTONE	5/5/5/5 mm
L/H Rear Tyre	275/70 R22.5 (D/D)	AMBERSTONE	5/5/5/5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	04/04/2020	Inspection Date	09/04/2020
Survey held at	FOCUS AUTO PTE LTD NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------