

ASS. REC. BY:

REF:

107/ 20003104/Kg

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SKN 4687 X Yr Regn: 03, 09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic c.c 1395

Colour

M. Grey A/C: Insured / Std / Nil / NA

Sp. Reading

120851 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

JHMF0 46209S 200 774

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: GY 205/55R16

R: Nil

BS / DUN / EXNOVA / GY / FS / LIZA / MITSUBISHI / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8 mm

Rear

R/Bal.

8 mm

L/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

7/4/20

D.O.I.

11/4/2020

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - R.S. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT202004-000170(00)

MS FIRST CAPITAL INSURANCE LTD

NO. 36

ROBINSON RD #16-01

CITY HOUSE

SINGAPORE 068877

Contact : -

Fax No. : 65073849

Date : 08/04/2020

Vehicle No. : SKN4667X

Make/Model : HONDA CIVIC

Mileage (km) : 0

Chassis No. : JHMF46209S200774

Accident Date : 07/04/2020 00:00:00

Claim No. : SHD4037C

Reference : JO202004-0226

Policy No. : D19MTPV01010584

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Front LH wheel bearing	1.0	113.40	113.40 ?
2	Front LH fender	1.0	537.00	537.00 ✓
3	Front LH fender signal lamp	1.0	18.20	18.20 ✓
4	Front LH fender innershield	1.0	104.30	104.30 ✓
5	Front LH fender innershield clip	8.0	3.50	28.00 ✓
6	LH wing mirror assy	1.0	541.90	541.90 X
7	Front LH door	1.0	925.20	925.20 ✓
8	Front LH door hinge	2.0	48.60	97.20 ✓
9	Front LH door catchea	1.0	48.50	48.50 ?
10	Front LH door lock	1.0	217.10	217.10 X
11	Front LH door rubber	1.0	104.70	104.70 ?
12	Front LH audio speaker	1.0	265.00	265.00 X
13	Front LH door regulator with motor	1.0	529.70	529.70 ?
14	Front LH door protector	1.0	107.00	107.00 ✓
15	Front LH door protector chrome	1.0	107.00	107.00 ✓
16	Rear LH door protector	1.0	97.10	97.10 ✓
17	Rear LH door protector chrome	1.0	97.10	97.10 ✓
18	LH rocker panel	1.0	269.60	269.60 ✓
19	Rear LH wheel bearing	1.0	264.60	264.60 X
20	Front LH door frame sticker	1.0	53.50	53.50 ✓
List Total :				4,526.10
20% Discount S\$				905.22
				3,620.88
SPECIAL NET :				
1	Front LH rim	1.0	350.00	350.00 ✓
2	Rear LH rim	1.0	350.00	350.00 X
SPECIAL NET Total S\$:				700.00
LABOUR :				
-	To change front LH & rear LH wheel bearing	1.0	140.00	140.00 ?
-	To conduct wheel alignment	1.0	75.00	75.00 60/
-	To transfer front LH door components to new door	1.0	80.00	80.00 60/
-	To spray rubberized under-coating	1.0	120.00	120.00 60/

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE NEXT PAGE

Page 1 of 2



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

MS FIRST CAPITAL INSURANCE LTD

NO. 36
ROBINSON RD #16-01
CITY HOUSE
SINGAPORE 068877

Contact : -

Fax No. : 65073849

Estimate : QUOT202004-000170(00)

Date : 08/04/2020

Vehicle No. : SKN4667X

Make/Model : HONDA CIVIC

Mileage (km) : 0

Chassis No. : JHMFD46209S200774

Accident Date : 07/04/2020 00:00:00

Claim No. : SHD4037C

Reference : JO202004-0226

Policy No. : D19MTPV01010584

S/No	Particular	Quantity	Unit Price	Amount S\$
	-To knock jackout damaged parts, panel beating,welding, align, refix and to renew accident parts	1.0	1,300.00	1,300.00 ^{900/}
	- Spray painting on affected & replace parts	1.0	1,400.00	1,400.00 ^{1100/}
				<u>3,115.00</u>

E. & O.E.

Total S\$: 7,435.88

GST 7% S\$: 520.51

Amount Due S\$: 7,956.39


for CITY AUTO PTE LTD