



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
CHIAM STELLA (ZHAN HUIQI)	Cust No/Name	/CHIAM STELLA (ZHAN HUIQI)
5 BUKIT BATOK STREET 25	Reg No/Reg Date	SMK3324J / 05/04/201
#13-11	Date In/Mileage	/ 0
SINGAPORE 658880	Chassis No	KNAF3416MK5031203
Contact No Mobile: 91726076	Engine No	G4FGJH722209
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	07/04/2020/ 15:51	QUE	261 / Edwin Caina	14545		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1100 2750.00
RENEW RR BUMPER							
REPAIR RR END PNL , BOOTLID & RHR FENDER							840 2100.00
E PNT98000							275.00
RESPRAY RR BUMPER , RR END PNL , BOOTLID , RHR FENDER & RR FLR PNL							
E PNT88000							30 50.00
REMOVE & REFIT RR FLR BOARD,TRIM & CARPET TO FACILITATE REPAIR							200.00
A 54900099							
CHECK WIRING ELECTRICAL SYSTEM							
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN-PRO TEST							
USING HI-SCAN PRO TEST							X 120.00
M SUNDRY							
APPLY ANTI CORROSION ON AFFECTED AREAS							80 100.00
E PNT88000							? 220.00
REMOVE & REFIT REVERSE SENSOR							X 40.00
M SUNDRY							20 50.00
SUPPLY REVERSE SENSOR							
M SUNDRY							
SUPPLY C&C BADGE							
M SUNDRY							
Sundries							
COVER-RR BUMPER				1.00	651.00	00.00	651.00
COVER-RR BUMPER LWR				1.00	241.00	00.00	241.00
COVER-RR BUMPER UNDER,LH				1.00	33.00	00.00	33.00
COVER-RR BUMPER FOG LAMP,RH				1.00	19.00	00.00	19.00
LAMP ASSY-SIDE T/SIGNAL,RH				1.00	181.00	00.00	181.00
EXTN WIRING ASSY-BWS				1.00	207.00	00.00	207.00
BEAM-RR BUMPER				1.00	318.00	00.00	318.00
STAY-RR BUMPER LH				1.00	65.00	00.00	65.00
STAY-RR BUMPER RH				1.00	65.00	00.00	65.00
ANTENNA ASSY-SMARTKEY				1.00	46.00	00.00	46.00
BRACKET-RR BEAM UPR MTG,LH				1.00	9.00	00.00	9.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
CHIAM STELLA (ZHAN HUIQI) 5 BUKIT BATOK STREET 25 #13-11 SINGAPORE 658880 Contact No Mobile: 91726076	Cust No/Name	/CHIAM STELLA (ZHAN HUIQI)
	Reg No/Reg Date	SMK3324J / 05/04/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5031203
	Engine No	G4FGJH722209
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSMQ0081	Cash	07/04/2020/ 15:51	QUE	261 / Edwin Caina	14545
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	BRACKET-RR BEAM UPR MTG, RH ?	1.00	9.00	00.00	9.00
M	BRACKET-RR BEAM LWR, CTR ?	1.00	6.00	00.00	6.00
M	BRACKET-RR BEAM LWR MTG ?	1.00	6.00	00.00	6.00
M	COVER-RR BUMPER UNDER, RH ?	1.00	33.00	00.00	33.00
M	BRACKET ASSY-RR BPR SIDE UPR, L ?	1.00	25.00	00.00	25.00
M	BRACKET-ASSY RR BPR SIDE UPR, R ?	1.00	31.00	00.00	31.00
M	LOGO ASSY-KIA SUB X	1.00	32.00	00.00	32.00
M	EMBLEM-CERATO X	1.00	28.00	00.00	28.00

Estimate

SURVEYOR NAME : Ram - Hg 90010068SURVEYOR SIGNATURE : RmDATE : 08/06/2021 @ 1030REMARKS : 4 daysResurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

	Nett	7,910.00
7% GST on	7910.00	553.70

Total Payable	8,463.70
---------------	----------

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or