

CS3/MSG19020488/Fvf3 -1

ASS. REC. BY: Ram REF: CS3/MSG19020488/Fvf3 Special Instruction:

Assignment (Office) 11/04/2020

From (Person): Crystal Lee Fievel Foo of MSG Date/Time: 11/04/2020 9:34pm

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SLP1638C Insured: SLX6540A

at Workshop in/s: Gum Asia Motorsports Tel: 9826 9998

of 561 Ayer's way # 04-04

Policy No: Claim No: 233514

Sum insured: 1000955317 Excess:

Make of Veh: (Client's Record) D.O.A. 15/11/2019

CA / REV / REP. / REV 24 HRS

Date/Time: 24/11/2019 Person Contacted: David H.O.D. Endorsement: IN/OUT

Date/Time Action/Instruction Volume/ID X

SLP1638C-X

SLX6540A-X

26/11 Crystal Lee said Merimen not created becos still pending some documents.

Dismantle: 20/11/2019

After repair: 25/11/2019.

APP. FOR BY RAMREF: MSIG

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

at

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLP1638CYr Regn: 07/JUN/2010Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Corolla Altis cc 1598Colour: white A/C: Insured / Std / NI / NASp Reading: 286055 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MTC53ZEE106174530Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Conti

Front

Rear

R/Bal: 5 mmR/Bal: 5 mmL/Bal: 5 mmL/Bal: 5 mmD.O.A: 15/11/19D.O.I: 19/11/19Survey held at Euro Asia automobileDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop orO/S rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range: \$3000-\$4000Repair days: 4 daysMV: \$14220.50PV: \$9839NV: \$4381.50

Date/Time, File Path to?

☐: Prel. Report

1)

☐: Final Report

Date/Time, File Path to?

3)

Report Format: PRS

Lump Sum / MP/1/3

Days Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐: Site Insp. \$5☐: Interview \$5☐: Tech. Insp. \$5☐: Mobilized \$5Survey Fee: 120

Transportation:

C + RS \$

Fuels

Other

TOTAL

11131