

CS3/AIG19019896/Gyf3 -1

22/03/2002

ASS. REC. BY:

REF:

~~CS3/AIG19019896/Gyf3 -1~~

Special Instruction:

Surveyor:

Loh Chee Heng

ASSIGNMENT (Office)

09/04/2020

From (Person):

~~Wong Foon~~

of

AIG

Date/Time:

~~11/11/19 9:29am~~

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKE 7014H

Insured:

SME 78145

at Workshop m/s

Y2K Audio Design

Tel:

96377738

of

Blk 160 San Ming Drive #106-13

Policy No:

Claim No:

336676260786

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 6/1/19

CA / REV / REP. / REV 24 HRS

mp

H.O.D. Endorsement:

Date/Time:

11/1/19 10:09am

Person Contacted:

Mr Lu

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SKE 7014H -x

SME 78145 -x

Dismantle: 12/1/2019.

ASS. REC. BY:

REF:

A1G

PRS

ASSIGNMENT

From:

Date: 11-11-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKG 7014H

at Workshop m/s

Y2K Audio Design

of

B1K 160 Sunning Drive #06-13

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$16K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKG 7014H

Yr Regn:

12 Mar 2010

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Scirocco c.c. 1390

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

184544

T/Radio: Insured / Std / NI / NA

Eng/No:

WVWZZZBZAV42864P

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

11-11-19

Survey held at

w/s

2:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 13 NOV 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Rep. Form:

DAR.

Lump Sum / E.B. / C.

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

180

Transportation:

S + RS \$

Photos

Others

TOTAL

11

101