COMFORTDELGRO 305393131 Our Job Ref No . ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 16. Apr. 2020 Date **FINALIZATION FORM** LKK Fax: RAM Attn Vehicle Reg No. : SHD3178K 9. Apr. 2020 Date of Accident: The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-1. The repair job shall bill to: NTUC **GBJ821X** 2. The finalized amount shall be: (a) Spare Parts after List discount (b) Labour Charges Total for Part-By-Part Repair Cost (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost \$1,000.00 3. 2 Estimated normal period for repairs: working days. 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days 5. Thank you for your assistance. We confirm the estimates and finalized amount Signature: Signature: Raws Name Name 6214 8316 Tel Date Fax 6546 8156 For Official Use Only

| ltem  | Amount | Document<br>Attached<br>Yes or No | Confirm By (Signature) | Remarks |
|---|--------|-----------------------------------|------------------------|---------|
| Rental Rate P/Day   |        | YES                               |                        |         |
| 2. Loss of Income Paid  |        | NO                                |                        |         |
| 3. Survey Fees  |        |                                   |                        |         |
| 4. LTA Search Fee   | \$7.49 |                                   |                        |         |
| <ol><li>Medical Fees (on behalf<br/>of driver, if applicable)</li></ol> |        |                                   |                        |         |
| 6 Overrun   |        |                                   |                        |         |

| Remarks:                                |  |
|---|--|
| Children                                |  |
| *************************************** |  |