

TAE/2007

ASS. REC. BY:

REF:

Special Instruction:

Surveyor

Monica Chung

ASSIGNMENT (Office)

13/04/2020

Specimen

From Person: Monica Chung of MSG Date/Time: 13/04/2020Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/ENV/MV/CS

To Inspect Vehicle No: FU 9935X Insured: SDS 8232Yat Workshop m/s: My car consultant pte Ltd Tel: of 53 Ubi Ave 1 #01-33Policy No: 29032696TMC Claim No: 604948Sum Insured: Excess: Make of Veh: D.O.A. 29/08/2019
(Client's Record)CA / REV / REP. / REV 24 HRS api H.O.D. Endorsement: Date/Time: 6.9.19 3.45p.m Person Contacted: Hui Qin Vehicle IN / OUT

Date/Time	Action/Instruction
	(X) Estimate Inspection - Kaki Bukit #01-68 Synergy
	SDS 8232Y - NA / MSG19015820/24 D.O.A. 29/08/2019
	FU 9935X - NA / MSG19015820/24 D.O.A. 29/08/2019
	Dismantle: 10/9/2019

Surveillance

REF:

MS67

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

\$ 500 - \$ 1000

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

PRE

Lump Sum / I.B.I: (\$

Veh No:

FU 9575X

Yr Regn:

Jun / 02

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda phantom c.c 197

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

94617

T/Radio: Insured / Std / NI / NA

Eng/No:

TA200 000 8959

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

100/80-17

R:

130/90-15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NET BELGR

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

06-05-19

Survey held at

W/S

4:55pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

\$ + RS. \$

Photos

Others

TOTAL