

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC3/AXA14006751/Kka3s2-1		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: STACEY NG		Date: 29-04-2020 Code: AXA2			
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SGV 9321R	Veh. Inspected	SHB 7855Z	
	Policy No.	P1014074	Coverage (\$)	0.00	
	Claim No.	C0308335	Excess (\$)	0.00	
	Assign From		Assign Date	01/01/1900	
2. Vehicle Particulars & Condition					
	Make & Model	CHEVROLET EPICA (A)	c.c	1991	
	Engine No.	HIDDEN	Year of Reg.	2012	
	Chassis No.	KL1LA69RJBB108008	Colour	WHITE / RED	
	Odometer	205090	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65R15	FALKEN	2 mm	
	L/H Front Tyre	195/65R15	FALKEN	2 mm	
	R/H Rear Tyre	195/65R15	WEST LAKE	7 mm	
	L/H Rear Tyre	195/65R15	WEST LAKE	7 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	05/04/2014	Inspection Date	08/04/2014	
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD			
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a.	a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	<b>5b.</b> Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				