ASS. REC. BY: Rosie REF: CS3/MSG 621A

COE EXPIRY: 2028/DEC

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 50K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMQ 4130M Yr From: 2009 / DEC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: VOLKSWAGEN SCIROCCO 1.4LAT c.c 1390

Colour GREY A/C: Insured / Std / NI / NA

Sp.Reading 115598 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZ13ZAV419591

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/40ZR18

R: 〃

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	11/04/2020	D.O.I.	15/04/2020

Survey held at KOK WANG

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or N/S FRT & O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair range 12K-13K - 10 days

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation:

Photos

Notes

TOTAL

Rep[redacted] Format :

Lump Sum / E.P.I. (%)