22/03/2002

ASS. REC. BY: | REF: CS3 / MSG20005185 / f3 | Special Instruction:

Surveyor:

ASSIGNMENT (Office)

Melinda

From (Person): Monica Chung Pei Zhen of MSIG Date/Time: 14.4.20

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMQ 4130M Insured: SMQ 2808E

at Workshop m/s Kj Car Repair Tel: 91839633

of 1 Soon Lee Street #06-40

Policy No: A287951044MCX Claim No: 623171

Sum Insured: Excess:

Make of Veh: D.O.A. 11.4.20
(Client's Record)

CA / REV / REP. / REV 24 HRS "NP" 15/4/2020 H.O.D. Endorsement:

Date/Time: 14.4.20 11.29 a.m Person Contacted: Mr Kok Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate.
	SMQ 4130M - X
	SMG 2808E - X