22/03/2002

ASS. REC. BY: | REF: CS4/ASM20005190/P f3 | Special Instruction:

Surveyor: Sherwin

SMART CLAIMS

ASSIGNMENT (Office)

From (Person): Cynthia Loh of ASM Date/Time: 13/04/2020

Estimated Cost: Bill to:

OD / ~~TP~~ / ~~WS~~ / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XD 3348Y Insured:

at Workshop m/s SNG AH TEE Tel: 62686183

of Blk 3 Pioneer Rd North #01-18 Singapore 628457

Policy No: Claim No: S0M02IV5

Sum Insured: Excess:

Make of Veh: D.O.A. 09/03/2020
(Client's Record)

INVESTIGATION

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 14/04/20@1.12pm Person Contacted: Samantha Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction ( ) Estimate
	XD 3348Y NA/INC19000073/h4 DOA: 02/01/2019