



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Ref: CC4/ASM20005205/Aba3q2 Date: 08/10/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKG 7311P	Veh. Inspected	SKX 5332C	
Policy No.	GA501831	Coverage (\$)	0.00	
Claim No.	S0M02M1U	Excess (\$)	0.00	
Assign From		Assign Date	14/04/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	RU11103592	Colour	SILVER	
Odometer	122818 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	215/60 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	215/60 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/04/2020	Inspection Date	15/04/2020	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	