

ASS. REC. BY

H-ANN

REF:

AG

ASSIGNMENT

From:

Date:

18/12/19

Estimated Cost:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMC 688X

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMC 688X

Yr Regn:

28/11/2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MIT EVO-10 GSR cc 1998

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

1808/80

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

CZ 4A000.4151

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

265/35/22R18

R:

265/35/22R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

57 mm

R/Bal.

57 mm

L/Bal.

5 mm

L/Bal.

5 mm

D.O.A.

4/12/19

D.O.I.

17/12/19

Survey held at

Triple-T

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

DAN = 10h

rpt days = 3 days

* SMC 688X

PRS case

* shortage police report statement

MV - 118000

PV - 32697

VV - 85300

RECEIVED 02 JAN 2020

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 2/1 - typist

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Inv (\$

☐

Weekend (\$

Survey Fee:

180

Transportation:

S + RS \$

Photos

Other:

11

TOTAL

191

Report Format:

Lump Sum / L.E.B.: