

ASS. REC. BY: Taufikh

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. 5101280287-01 (23/06/2019-22/06/2020)

Claims No. MT/1091443 -002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD 3402 MYr Regn: 2016, JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Q / Prime Mover /

Truck / Trailer or

Make: Hyundai 140c.c. 1685Colour Blue

A/C: Insured / Std / NI / NA

Sp. Reading 601874

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM HCB4/YM 64093231Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / ST Rim / STD A/Rim orTyre Size: F: 205/60R16R: 16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 15/4/20Survey held at Comfort Loging

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

20/04/20 Taufikh finalised with Mr Lim LS \$2350, 3 days.

(Red \$2773.44, 54%)

Date/Time, File Pass to?

☐

Preli. Report

20/04 Typist

☐

Final Report

Date/Time, File Return to?

2)

Rep. Format: TP

Lump Sum / 12% 2350

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Survey Fee:

Transportation

\$ - RS \$

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

NTUC - 4S
LKK - Taufik.

Date: 15.04.2020

Time: 15:52:56

Page: 1/2

IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305393356
REGN NO : SHD3402M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 28.07.2016
DATE/TIME IN : 15.04.2020 12:15
ACCIDENT DATE : 15.04.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	FRT BUMPER	1	1,052.20	20.00	841.76	de ✓
0002 04-01-0103-0638-G	FRT BUMPER UPR BRKT RH	1	22.40	20.00	17.92	de ✓
0003 04-01-0103-0640-G	FRT BUMPER BRKT RH	1	24.60	20.00	19.68	de ✓
0004 04-01-0103-4991-G	FRT BUMPER GRILLE RH	1	93.60	20.00	74.88	7
0005 04-01-0103-0782-A	HEADLAMP RH	1	1,388.00	20.00	1,110.40	cm ✓
0006 04-01-0103-2164-A	RADIATOR GRILLE	1	1,480.00	20.00	1,184.00	X
0007 04-01-0103-2175-G	RADIATOR GRILLE H EMBLEM	1	39.50	20.00	31.60	X
0008 04-01-0103-0652-G	BONNET HINGE RH	1	41.00	20.00	32.80	X
0009 04-01-0103-0573-A	FRT FENDER RH	1	663.00	20.00	530.40	Rx

SUB-TOTAL : 3,843.44

JOB NATURE

0000 20-05	Frt Fender Adv.Sticker RH	100.00	de ✓
0001 PB	PANEL BEATING	600.00	420.

COMFORTDELGRO ENGINEERING PTE LTD

Date: 15.04.2020

REPAIR ESTIMATE

HTUC-45

Time: 15:52:56

Page: 2/2

B

LKK - Taufik

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305393356
REGN NO : SHD3402M
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 28.07.2016
DATE/TIME IN : 15.04.2020 12:15
ACCIDENT DATE : 15.04.2020

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT	
0002 SP	SPRAYPAINT CHARGE	500.00	400.
0003 17-01	CHECK ALL LIGHTING	40.00	30.
0004 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	30.
		SUB-TOTAL : 1,280.00	

TOTAL : 5,123.44

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749
wp'

15/4/2020 1615

Lumpsum

Resurvey after repair.

03 days

taufik@lkkauto.com
sur@lkkauto.com