

22/03/2002

ASS. REC. BY:

REF: <sup>3</sup>CS/CTI 20005252/RVf3 Special Instruction:Surveyor: ROSA ASSIGNMENT (Office)From (Person): Addins chng of CTI Date/Time: 16.4.20 4.14p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / ~~FD~~ / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKL 4348C Insured: YP 9428Kat Workshop m/s Han Car Repair Tel: 97777266of 1001 Bukit merah LAM #01-49Policy No: DMKUSN 1833 5914011 Claim No: SNM 20020766

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 8.4.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS <sup>mp</sup> H.O.D. Endorsement: \_\_\_\_\_Date/Time: 16/4/20 5.00p.m Person Contacted: Susan Vehicle: IN/OUT

| Date/Time      | Action/Instruction ( X ) Estimate                      |
|----------------|--------------------------------------------------------|
|                | <u>YP 9428K - X</u>                                    |
|                | <u>SKL 4348C - X</u>                                   |
| <u>20/4/20</u> | <u>@ 1130am Susan said no est, pass to lawyer</u>      |
| <u>21/4/20</u> | <u>Submit PRS repair range \$2000 - \$3000, 3 days</u> |


ASS. REC. BY: JamesREF: CS/CTI 2000S 252/R1 v f38276  
COC FPIRy: 2028/NOV

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SKL 4348C  
 at Workshop m/s: Ham car  
 of: 1001, BUKIT NEAH Lp 3 #01-49  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: 45K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKL 4348C Yr F: 2009 FEB  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: TOYOTA WISH 1.8 A CC: 1744  
 Colour: BLACK A/C: Insured / Std / NI / NA  
 Sp. Reading: 185219 T/Ratio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: 5100R 12W 403001976  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Order / Jammed / Leaked / Burnt or  
 Brake: Order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/65R15  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 08/04/2020 D.O.I. 17/04/2020  
 Survey held at Ham car repair

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rootcap or

FRG O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 3

1)

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2) 2/4 - typistAdd Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Weekend (\$)Rep. Form: mainmen

Lump Sum / L.P.I. /

Survey Fee

Transportation

PS - 9

Chassis

Body

Paint

Total