

ASS. REC. BY:

REF: CS/CT1 20005247 / f3

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person):

Ben Tang

of

C71

Date/Time:

17.4.20 11.57am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLK 11714

Insured:

SGN 8804m

at Workshop m/s

Estee m Performance

Tel:

8799 0066

of

5033 Amt Industrial Park 2 #01-259

Policy No:

Claim No:

S/V/M 200201574

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.Q.A.

12.2.2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

17.4.20

12.03 p.m

Person Contacted:

Carmen

Vehicle IN/OUT

N/OUT

Date/Time	Action/Instruction (✓) Estimate.
	SLK 1171H - CS/F(24005924/E+115K2) ROA - 16/07/2017
	SGN 8804m - X