



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20005301/Ayf3q2

(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRESINGAPORE
239924

Date : 09-11-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGW 2266H	Veh. Inspected	SKW 1567Z
Policy No.		Coverage (\$)	0.00
Claim No.	C10006198	Excess (\$)	0.00
Assign From	STANLEY LAI	Assign Date	20/04/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ B 200	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WDD2462432J195278	Colour	WHITE
Odometer	148734	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	MICHELIN	6 mm
L/H Front Tyre	225/45 R17	MICHELIN	6 mm
R/H Rear Tyre	225/45 R17	MICHELIN	6 mm
L/H Rear Tyre	225/45 R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/04/2020	Inspection Date	21/04/2020
Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	-----------------------