

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC20005304/Fyf3e2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	29-05-2020 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SJH 7646E	Veh. Ir	Veh. Inspected SHC 1174P		
	Policy No.	5102232954-01	Coverage (\$)		0.00	
	Claim No.	MT/1091545-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	20/04/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2020	
	Chassis No.	KMHC851CVLU190705	Colou	r	BLUE	
	Odometer	2064	Steering		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	MICHE	LIN	9 mm	
	L/H Front Tyre	195/65 R15	MICHE		9 mm	
	R/H Rear Tyre	195/65 R15	MICHE		9 mm	
	L/H Rear Tyre	195/65 R15	MICHE		9 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	17/04/2020	Insped	tion Date	20/04/2020	
	Survey held at	held at COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					