

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

NLMC-PIP

Date: 18.04.2020

Time: 10:34:03

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305393958  
 REGN NO : SHC1174P  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G3)  
 DATE OF REGN : 08.04.2020  
 DATE/TIME IN : 18.04.2020 08:30  
 ACCIDENT DATE : 17.04.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0576-G PANEL ASSY-QUARTER OUTER 1 L 1,768.30 20.00 1,414.64 x(R)  
 0002 28-01-0302-2017-A FUEL TANK LID (PETROL ONL 1 N 15.00 10.00 13.50 nec ✓

SUB-TOTAL : 1,428.14

JOB NATURE

0000 PB PANEL BEATING 960.00 \$320  
 0001 SP SPRAYPAINT CHARGE 300.00 \$200

SUB-TOTAL : 1,260.00

Jumani

TOTAL : 2,688.14

MVA NAME &amp; SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME &amp; SIGNATURE

DATE :

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram (LKK)  
 20/04/2020 1508  
 Ram@lkkauto.com  
 8862278  
 (P/P) 2nd repair photo  
 @repair-deg