



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20005334/Uga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 16-07-2020



ATTN:RICHARD

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGJ 1383C	Veh. Inspected	SLX 2799Y
Policy No.	GA047050	Coverage (\$)	0.00
Claim No.	S0M02MN1	Excess (\$)	0.00
Assign From		Assign Date	22/04/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E 200 (A)	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WDD2120482A415106	Colour	BLACK
Odometer	148091	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R18	PIRELLI	6 mm
L/H Front Tyre	245/40 R18	PIRELLI	6 mm
R/H Rear Tyre	245/40 R18	GOODYEAR	6 mm
L/H Rear Tyre	245/40 R18	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/04/2020	Inspection Date	22/04/2020
Survey held at	ABWIN SERVICE PTE LTD 17 KAKI BUKIT ROAD 4 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------