



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

POON SIANG SEOW

Ref : CS/TP20005337/Kvf3e2

No.160 SIN MING DRIVE  
#05-13 SIN MING AUTOCITY  
SINGAPORE 575722

Date : 11-05-2020



ON BEHALF OF JIUNN MING ALLAN

Code : TP520

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	<b>Veh. Inspected</b>	SJA 9288D
<b>Policy No.</b>	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	<b>Assign Date</b>	21/04/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA ALTIS (A)	<b>c.c</b>	1598
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	MR053REH104558731	<b>Colour</b>	METALLIC RED
<b>Odometer</b>	82308	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	215/45 R17	GOODYEAR	7 mm
<b>L/H Front Tyre</b>	215/45 R17	GOODYEAR	7 mm
<b>R/H Rear Tyre</b>	215/45 R17	GOODYEAR	7 mm
<b>L/H Rear Tyre</b>	215/45 R17	GOODYEAR	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	21/04/2020	<b>Inspection Date</b>	21/04/2020
<b>Survey held at</b>	POON SIANG SEOW No.160 SIN MING DRIVE #05-13 SIN MING AUTOCITY SINGAPORE 575722		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**