

ASS. REC. BY:

REF:

CS3/SMO20002549/Gsf3-1

Special Instruction:

Supervisor:

GA

Ruth Chua

ASSIGNMENT (Office)

23/04/2020

From (Person):

Grafed

of

SMD

Date/Time:

23/04/2020 11:13am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLJ 7155 X

Insured:

FBJ3222E

at Workshop m/s

Apex Motoring

Tel:

9169 0825

of

25 Kaki Bukit Road 4 # 01-SS Synergy

Policy No:

Claim No:

CMPD2000670/RUC

Sum Insured:

Excess:

Make of Veh:

D.O.A.

05/02/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

lwp)

H.O.D. Endorsement:

Date/Time:

11:55am @ 13/4/2020

Person Contacted:

Ms. Lim

Vehicle IN/OUT

Date/Time	Action/Instruction
	SLJ 7155 X - X
	FBJ 3222E - X
14/02/20	@ 11:07 am checked with Ms. Lim, no estimate.

ASS. REC. BY:

bil
PRS

Veh. No.

ASSIGNMENT

From

Date

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Apex Motoring

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLJ 7155 X

Yr Regn:

- 2016

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Altis

C.C

1598

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

248525

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053REH 10.455 7450

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55 R16

R:

17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

Survey held at

w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal.

6

mm

L/Bal.

6

mm

D.O.I.

13-02-20

4pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$7000 - \$8000

14/2/2020

Dismantle: 14/2/2020

Date/Time, File Pass to?

1) 14/02/20
Typ: St

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 7

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Wash and (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Notes

TOTAL

PAID TO POLICE

Long Sum / L.P.R.

PRS