



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA			Ref: CC4/ASM20005368/Uga3q2 Date: 05/01/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SLA 551D	<b>Veh. Inspected</b>	GBC 1175H
	<b>Policy No.</b>	VFX/P1305555	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	S0M02MYV	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>		<b>Assign Date</b>	23/04/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	NISSAN NV200 (M)	<b>c.c</b>	1461
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2011
	<b>Chassis No.</b>	JN1YBAM20U0003289	<b>Colour</b>	SILVER
	<b>Odometer</b>	209883 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	175/70 R14	JKT TYRE	6 mm
	<b>L/H Front Tyre</b>	175/70 R14	JKT TYRE	6 mm
	<b>R/H Rear Tyre</b>	175/70 R14	JKT TYRE	6 mm
	<b>L/H Rear Tyre</b>	175/70 R14	JKT TYRE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	22/04/2020	<b>Inspection Date</b>	24/04/2020
	<b>Survey held at</b>	AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (AIM) 23 KAKI BUKIT AVE 5 #04-01 (SOUTH WING) SINGAPORE 415933		
<b>5a. Remarks</b>				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	