

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ASM20005368/UKQ3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBC 1175H

at Workshop m/s

AM

of

Insured:

SLA 5510

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value:

12k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

995-E

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBC 1175H

Yr Regn:

29/4/11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M)

Make:

Nissan NV200

c.c

1461

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

209883

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1YBAM2040003289

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

JKT tyre

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

22/4/20

D.O.I.

24/4/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rpt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LT A 7222 on 28-4-2011
with 4778

29/4/20 4/5 \$4000 confirmed with kelvin

Date/Time, File Pass to?

☐: Preli. Report

Days Of Repair:

1)

☐: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

Site Insp (\$

) S + RS. SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

)

TOTAL



Automobile Integrated Management Pte Ltd

ESTIMATE

AVA

Our Ref: AC2020031/TP/GBC1175H-22.04.2020

Automobile Integrated Management Pte Ltd
Co. & G.S.T. Reg no. 201605297G
Office: 28 Sin Ming Lane #07-147 Midview City
Singapore 573972
Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing)
Singapore 415933
Email: automim.claim@gmail.com Tel: 9119 8371

Vehicle number: GBC1175H

Vehicle Made & Model: NISSAN NV200

Items	Qty	List Items
1	1	Front bumper
2	2	Front bumper side retainers - L/R @ 28.60
3	1	Front fender - LH
4	1	Front fender lamp
5	1	Front fender bracket
6	1	Front fender inner panel
7	1	Front fender inner shield
8	1	Front door - LH
9	1	Front door side mirror
10	1	Front door glass outer moulding
11	1	Front door glass run channel
12	1	Front door w/strip
13	1	Front door checker
14	1	Front headlamp - LH
15	1	Front headlamp panel
16	1	Front headlamp lower garnish
17	1	Front shock absorber - LH
18	1	Front shock absorber top mount
19	1	Front lower arm - LH
20	1	Front knuckle arm - LH
21	1	Front wheel hub cap - LH
22	1	Front wheel hub bearing - LH
23	1	Front anti roll bar
24	1	Front anti roll bar link

1651.80

not added
Lah
2/5 = 4000/
5 days
24/4/20

Amount \$
512.20 ✓
57.20 ✓
548.80 ✓
42.20 ✓
89.50 X
481.50 ✓
121.40 ✓
1,696.60 ✓
481.90 X
121.60 X
155.30 X
122.30 ✓
65.50 X
454.60 ✓
126.60 X
344.60 ✓
384.60 X
144.50 X
433.40 X
486.90 X
181.90 ✓
415.50 ✓
420.60 X
86.90 X

Sub-total	7,976.10
Less 10%	797.61
Total List	7,178.49

502

Special Nett Items

25	1	Front wheel rim - LH
26	1	Front tyre
27	1	R.O.V sticker
28	1	Advertisement sticker
29	1 set	Front bumper clips
30	1 set	Front fender inner shield clip

180.00 X
200.00 X
45.00 30
180.00 80
35.00 ✓
35.00 ✓

Total Special Nett 675.00

<u>Labour charges</u>		
31	To check wheel alignment	120.00 60
32	To remove, refix front undercarriage	300.00 100
33	To check front electrical wiring	50.00 20
34	To respray undercoating	120.00 60
35	To respray painting and etc	1,080.00 600
36	Panel beating, cut, weld remove & replacing above parts	1,200.00 600
Total Labour		2,870.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

10,723.49

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7-4905.40
 502
 1-2452.70
 S.N -180.00
 L- 1440.00
 4072.7