



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG			Ref: CC4/ASM20005375/Uea3q2 Date: 08/03/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 53L	Veh. Inspected	GBF 9143G	
Policy No.	CN055440	Coverage (\$)	0.00	
Claim No.	S0M02N03	Excess (\$)	0.00	
Assign From		Assign Date	24/04/2020	
2. Vehicle Particulars & Condition				
Make & Model	FIAT DOBLO CARGO MAXI (M)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZFA26300006F11505	Colour	WHITE	
Odometer	73470 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	HANKOOK	6 mm	
L/H Front Tyre	195/60 R16	HANKOOK	6 mm	
R/H Rear Tyre	195/60 R16	HANKOOK	6 mm	
L/H Rear Tyre	195/60 R16	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/04/2020	Inspection Date	24/04/2020	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	