



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Ref: CC4/ASM20005402/Aea3q2 Date: 13/07/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJE 8191J	Veh. Inspected	SLL 7163L
	Policy No.	VFX/P2371570	Coverage (\$)	0.00
	Claim No.	S0M02N2K	Excess (\$)	0.00
	Assign From		Assign Date	27/04/2020
2. Vehicle Particulars & Condition				
	Make & Model	SUBARU LEVORG	c.c	1600
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JF1VM4K55GG002582	Colour	WHITE
	Odometer	49025 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R18	DUNLOP	6 mm
	L/H Front Tyre	225/45 R18	DUNLOP	6 mm
	R/H Rear Tyre	225/45 R18	DUNLOP	6 mm
	L/H Rear Tyre	225/45 R18	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/01/2020	Inspection Date	28/04/2020
	Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	