ASS. REC. BY:	CS/TP20005414/Kqf3
Kennerh	
From:	ASSIGNMENT
Estimated Cost:	Veh No: SUK 8622 C Yr Regn: 02/02/2017 Type: M.Car / M. Orcio / Bus vivi
OD MPTWS / TP RES / OD RES / EVA / INV / MV	Type: M.Car / M.Cycle / Bus / Van / Lony / Taxl / Prime Mover / Truck / Traller or
To Inspect Vehicle No:) Tailer or
at Workshop m/s RC Ard	Make: Toy hish ss 1780
of RC Ave	Colour to M
Insured:	
Policy No.	Eng/No:
Claims No.	CNO: 77066200
Sum Insured: Excess:	Gen. Cond: Good / Fair / Poor / Burnt
(Client's Record)	Sleering: Inorder'/ Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: Nil / S/Rim / STO A/Rim or
(Policy Condition)	
Remark: The veh had commenced its	Tyre Size: F: 195/65R15
repair at the time of inspection.	O/S BS / DUN / EXNOVA / GY / FS / LIZA MIC OHTSU / PIR / SUMI /
Bal. or Market Value:	TOYO / YOKO or
IDAC Application	Front
GIA / DD C	R/Bai. Rear
Est Repaire: O.4 C.F.	UBal. mm R/Ba! mm
Lum Cum.	D.O.A. 22/4/20 Imm
3 Val.: Yes or No	Survey held at D.O.I. 24/4/2020
CA / REV / REP. / 24 HRS	
Date:Person Contacted: Vehicle: IN /	Des. of Damages : Frt Rear I O/S / N/S / U/C / Rooftop or
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Est not ned	anected due to collision.
LS \$2050, 4 days.	
(Red \$1912.40, 48%)	
oto/Time, File Pass to? : Prell. Report	
22/05 Typist : Final Report	Days Of Repair: 4
uto/Fine, File Return to?	Resurvey No. of Trip: 2 Survey Fee:
Add Fe	Transportation
, Add Le)_S+RS. SI
port Format: TP	: Interview (\$
mp Sum / I.B.I: (\$ 2050	Tech Invs (\$) Others
	Weekend (S)
	TOTAL





Police Station Of Origin: Bedok South N.P.C 20 Chai Chee Drive SINGAPORE 469045 Tel No: 1800-2448999 1 of 3 Report No. T/20200422/2041

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/04/2020 18:58		Vide Repor': No.: G/20200422/0206		Station Diary No.: 40	
Informan	"s Partiqu	iars · · · · · · · ·			
Name of I LIM HOOI			Address: * APT BLK 480 SIGLAP RC	OAD #03-81 SING	GAPORE 454855
ID Type / NRIC NO	ID No.: / S160910	0F	Contact No.: Home/Office:	Mobile: 98	570269
Nationality SINGAPO		EN .	Email:		,
Sex: Male	Age: 56	Date of Birth: 02/12/1963	Type of Informant: Driver		
Race: Chinese	n)	•	Language: English	Institution	/ School Name:
Occupation TECHNIC		CE OFFICER	Driving Licence Informatio	n: Date of Ex	piry:

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 22/04/2020 17:2		Type of Location: T-Junction
Location: Junction of Road CHAI CHEE AVE CHAI CHEE ROA T-Junction	NUE	•			
Weather: Sunny		Road Surface: Dry	•	Road 40 Kn	Speed Limit: n/h
Traffic Flow: Two Way	,	Traffic Control: Traffic Light - Worl	king	Traffic Mode	c Volume: rate
Type of Collision:	Vehicles - Head To R	ear			ne conveyed by lance:

Details of V	ehicle Involved			MANUAL PROPERTY AND		
Vehicle No.	中的dealle	Mare 4 F 3.	Model -	Secolor - 11	Candition.	No of Passenger
PMK120	Lorry				Slightly Damaged	2
SLK8622C	Car				Slightly Damaged	1

Details of Pease Plausined	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





Police Station Of Origin: Bedok South N.P.C 20 Chai Chee Drive SINGAPORE 469045 Tel No: 1800-2448999 2 of 3 Report No. T/20200422/2041

CONTINUATION OF REPORT

•	•	•	•	
Drivers Services		Carried Co.		
Name	LIM HOON CHING	Ŕ.,	ÌD No.	S1609100F
Related Vehicle	NIL		Contact No.	98570269
Hospital/Clinic	NIL .		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Disch	narge NIL	
No. of Days gran	ted Medical Leave NIL	Degree of		
Daver(中国)	Part Control of the C		中华 中华	的是他们的
Name	CHEW TIEM SIEW	٠,	ID No.	A37838220
Related Vehicle	NIL		Contact No.	0164254515
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 5 Date of Expiry: 26/12/2021
Date Treatment	NIL	Date Disch		
No. of Days granted Medical Leave NIL , Degree of Injury NIL				

Brief Details.

On 22/04/20 at about 1715hrs, I was driving my car SLK8622C along Chai Chee Ave towards Chai Chee Road.

My car was on stationary and stopped at the traffic light, when another vehicle number PMK120, a lorry with a container, hit the rear of my car. My car attained damages and bent at the rear tailgate and bumper. I did not see any visible damages to the lorry.

Nobody was injured.

We exchanged particulars and I called for the police. Traffic police and the police also arrived at the incident location and they advised me to lodge this police report vide incident number G/20200422/0206.