

ASS. FED. BY:

Steve

REF:

IV

22026 (f3)

ASSIGNMENT

From:

Date:

18/12/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLR 23562

at Workshop m/s

ET403

of

30 Bt Bantok Wessant

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLR 23562

Yr Regn:

7/8/17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra

c.c

1591

Colour:

Belge

A/C: Insured / Std / NI / NA

Sp. Reading

35743

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH10841CMJU537321

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

5

mm

L/Bal:

5

mm

D.O.A.

7/12/19

D.O.A.

18/12/19

Survey held at

ET403

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/2/20

Mr- 65k

Final- \$2,272.72, 3 days (Mr Lee) (Red & 216x.92, 491%)

Date/Time, File Pass to?



: Preli. Report

1) 14/2 transfer



: Final Report

Date/Time, File Return to?

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

250

Transportation:

S + PS: \$1

Add Fee:



Site Insp (\$)