

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





NTU	NTUC INCOME INSURANCE CO-OPERATIVE LTD			NS/INC20005460/Fyf3s2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	14-05-2020		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLT 8027Z	Veh. II	nspected	SH 9647H	
	Policy No.	5103241500-01	Cover	age (\$)	0.00	
	Claim No.	MT/1091888-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	28/04/2020	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year c	of Reg.	2018	
	Chassis No.	KMHC851CVKU115143	Colou	r	BLUE	
	Odometer	213206	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	DAVAN	ITI	8 mm	
	L/H Front Tyre	195/65 R15	DAVAN	ITI	8 mm	
	R/H Rear Tyre	195/65 R15	DAVAN	ITI	9 mm	
	L/H Rear Tyre	195/65 R15	DAVAN	ITI	9 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT AND FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	27/04/2020	Inspection Date 28/04/2020			
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					