




Service Request Details

Claim
SOM02MH6

Reference
None 

Loss Date
April 15, 2020

Report Date
Apr 17, 2020 12:00:00 AM

Request Date
April 29, 2020

Due Date
April 29, 2021

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss
Own Damage

Services
Accelerated workshop survey

Actions

Next Step
Finish the work

Complete Work

More ▾

Vehicle Information

Incident Vehicle Registration #
SKE9898K

Model
SL350 3.5

Service Address

, , ,

Primary Contact/Insured

ANG BOON HOCK
215 LORONG 8 TOA PAYOH, #07-721, 310215, Singapore
96618677

Claim Handler

OH Vale
6568804897
vale.oh@axa.com.sg

Additional Instructions
XS-\$700/- No auth as Insured may want to claim against C & C on manufacture fault. Attn: Bryan Ang...
(expand)

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message