





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/05/2020

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB1622J
Case Reference Number	BUS/04/20/5007
Registration Date	13/2/2015
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Song Zhaoliang
Type of Accident	Side Swipe
Accident Date and Time	3/4/2020 8:00 AM
Accident Reported Date and Time	3/4/2020 10:15 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24106753
Special Instruction to ARC,if any	SMB1622J-RIGHT REAR PORTION SLL4196L (TP) INSURED WITH AIG
Prepared Date and Time	29/4/2020 4:00 PM
Chassis Number	WMAA22ZZ2F7002606
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$878.00	\$708.00
Total Spare Part Cost	\$160.00	\$160.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,568.00	\$1,133.00
Lump Sum Total	\$0.00	\$1,150.00
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	30/04/2020 10:25 AM	30/04/2020 4:39 PM
Signature		
Remarks		L/S repair

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/05/2020

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.				\$530.00				\$265.00	
Total Labour				\$530.00				\$265.00	
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
TO PUTTY & RESPRAY				\$878.00				\$708.00	
Total Spray Painting & Panel Beating				\$878.00				\$708.00	
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			SMRT LOGO	1.00	\$200.00	0.00	\$200.00	Replace	Replace
Total					\$200.00		\$200.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

200
- 20%

160
265
708

1,133

215
\$ 1,150

2 days.