ASS. REC. BY: Kenneth

REF: CTZ/2000548/Kk93

C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s City Auto

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 days Res.: Yes or No

Lum Sum: 1.B.I % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMQ 2599H Yr Regn: 11, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Wagon

Make: Toy Noah c.c 1797

Colour M. Black A/C: Insured / Std / NI / NA

Sp.Reading 90448 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZWR80 - 0412278

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rlm / STD A/Rlm or _____

Tyre Size: F: 195/65R15

R: —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Westlake

Front		Rear	
R/Bal.	7 mm	R/Bal.	9 mm
L/Bal.	7 mm	L/Bal.	9 mm

D.O.A. 28/4/20 D.O.I. 30/4/2020

Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
13/5	Liaise & Good. Confirmed

Date/Time, File Pass to?

1) _____

Date/Time, File Return to?

2) _____

☐ : Prell. Report

☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ Tech Invs ($ _____)

☐ Weekend ($ _____)

Survey Fee: _____

Transportation: ___ $ + RS. ___ SI

Photos _____

Others _____

TOTAL _____

Report Format :

Lump Sum / I.B.I: ($ _____)

CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT202004-000531(00)

Date : 30/04/2020
Vehicle No. : SMQ2599H
Make/Model : TOYOTA NOAH HYBRID 1.8X CVT

CHINA TAIPING INSURANCE (S) PTE LTD
NO. 3
ANSON RD
SPRINGLEAF TOWER
SINGAPORE 079909

Not Authorise
Resurvey B4 paint
8 days

Contact : -

Fax No. : 62247175

Mileage (km) : 0
Chassis No. : ZWR800412278
Accident Date : 28/04/2020 00:00:00
Claim No. : YP3996B
Reference : JO202004-0650
Policy No. : 19-MK823000-R00

S/No	Particular	Quantity	Unit Price	Amount S$
	LIST ITEMS :			
1	RH wing mirror motor	1.0	1,081.75	CM 1,081.75
2	RH wing mirror cover	1.0	122.60	122.60
3	Front RH door	1.0	1,481.30	1,481.30
4	Front RH door outer moulding	1.0	CUT 141.70	141.70
5	Front RH door outer handle	1.0	347.60	347.60
6	Front RH door outer handle cap	1.0	41.95	41.95
7	Front RH door outer handle bracket	1.0	298.47	298.47
8	Front RH door lock	1.0	604.70	604.70
9	RH sliding door	1.0	1,621.70	1,621.70
10	RH sliding door lock	1.0	925.70	925.70
11	RH sliding door sensor	1.0	Dual Bm 1,411.79	1,411.79
12	Rear RH fender	1.0	1,144.50	1,144.50
13	Front RH Door Glass	1.0	856.70	856.70
14	Front RH quater glass	1.0	359.70	359.70
15	Front RH door frame sticker - frt	1.0	47.60	47.60
16	Front RH door frame sticker - ctr	1.0	98.70	98.70
17	Front RH door frame sticker - rear	1.0	67.83	67.83
18	RH sliding door frame sticker - side	1.0	67.70	67.70
19	RH sliding door frame sticker - top	1.0	75.33	75.33
	List Total :			10,797.32
	25% Discount S$			2,699.29
				8,098.03
	SPECIAL NET :			
1	Glass sealant	2.0	40.00	80.00
	SPECIAL NET Total S$:			80.00
	LABOUR :			6cl
	- To remove and refit door trims and components	1.0	200.00	200.00
	- To remove and refit front RH quater glass	1.0	100.00	100.00 5a
	- To remove and refit rear RH fender glass	1.0	100.00	100.00 8a
	- To remove and refit trims and seats	1.0	180.00	12d 180.00
	- To deactives and reactives power door system and use diagnostic computer to check and clear fault	1.0	200.00	200.00 12a

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CONTINUE NEXT PAGE

CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel 9823 9898
Co. Reg. No.: 199503435C **GST Reg. No.: M2-8920979-4**

Estimate : QUOT202004-000531(00)

CHINA TAIPING INSURANCE (S) PTE LTD
NO. 3
ANSON RD
SPRINGLEAF TOWER
SINGAPORE 079909

Contact : -

Fax No. : 62247175

Date : 30/04/2020
Vehicle No. : SMQ2599H
Make/Model : TOYOTA NOAH HYBRID 1.8X CVT

Mileage (km) : 0
Chassis No. : ZWR800412278
Accident Date : 28/04/2020 00:00:00
Claim No. : YP3996B
Reference : JO202004-0650
Policy No. : 19-MK823000-R00

S/No	Particular	Quantity	Unit Price	Amount S$
	-To knock jackout damaged parts, panel beating,welding, align, refix and to renew accident parts	1.0	1,300.00	100% 1,300.00
	- Spray painting on affected & replace parts	1.0	1,200.00	1100% 1,200.00
				3,280.00

E. & O.E.

Total S$:	11,458.03
GST 7% S$:	802.06
Amount Due S$:	12,260.09

for CITY AUTO PTE LTD