

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/11120005497/Uea3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GLA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLR9K497 Yr Regn: 8117

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Mazda 3

C.C 1496

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 188856

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F:

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/5/20 2/5 @ 1400 confirmed with MR Wong

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

GST:201004495R RCB NO:201004495R

LKK: Ashur

Not Authorised
Haler
30/4/20
L/s 1400/
3 days.

M/S : INDIA INTERNATIONAL INSURANCE**Estimate No: M00153****Date: 30-Apr-20****Veh Reg No : SLR9449T****Make/Model: MAZDA3****Chassis No: JM6BN22A8H0162668****Engine No: P520454862****Reg. Date : 24/07/2017****ATTN: Motor Claim Department****Your Ref No: SLR9449T****Claim Type: THIRD PARTY CLAIM****Accident Date : 28.04.20****Estimate Repair Cost to Vehicle No : SLR9449T**

PAGE:1/1

S/N	Description	Quantity	Unit	Price S\$	Amount S\$
<u>NETT PRICE</u>					
1	Front Door - LH	1	PCS	1046.20	1046.20 X
2	Front Door Rubber - LH	1	PCS	246.40	246.40 X
3	Rear Door - LH	1	PCS	1024.40	1024.40 ✓
4	Rear Door Hinge Lower - LH	1	PCS	50.20	50.20 X
5	Rear Door Rubber - LH	1	PCS	226.40	226.40 X
TOTAL				2593.60	2593.60
Less 20%				2074.88	2074.88

LABOUR CHARGES

6	Panel Beating	300	750.00
7	To Remove & Refit Door Assy	50	160.00
8	To Check Wiring	11 X	80.00
9	To Spray Paint	600	750.00
TOTAL			1740.00

OVERALL TOTAL 3814.88

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR FOCUS AUTO PTE LTD

P-1024.4
202
P-879.52
L-950.00
1769.52
202
1418

AUTHORISE SIGNATURE