

ASS. REC. BY:

FASNE

REF:

CS3/A1420005511/R15F3

4331

COE EXP. RY: 2025/Nov

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FZ 8375H

at Workshop m/s EQUIPMENT EXTREME

of BLK H001, DEPT RD, DEPT LK #01-10

Insured: AIG

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 8K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FZ 8375H Yr Regn: 2005 / NOV

Type: M.Car (M.Cycle) Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA CB 400 c.c. 399

Colour: MULTI A/C: Insured / Std / NI / NA

Sp. Reading: 348023 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JH2NC39976M100040

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/60ZR17

R: 160/60ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or METZLER

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. mm L/Bal. mm

D.O.A. 27/04/2020 D.O.I. 04/05/2020

Survey held at EQUIPMENT EXTREME

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S & O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

1)

Rep. Form: _____

Lump Sum / L.B. / C

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

/lta/vrl/action/enquireRebateByPublicBeforeDeregInput?FUNCTION_ID=F0304009TT

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	433I
Vehicle No.:	FZ8375H
Vehicle to be Exported:	No
Intended Deregistration Date:	04 May 2020
Vehicle Make:	HONDA
Vehicle Model:	CB400
Primary Colour:	White
Manufacturing Year:	2005
Engine No.:	NC23E3000040
Chassis No.:	JH2NC39975M100040
Maximum Power Output:	-
Open Market Value:	\$7,426.00
Original Registration Date:	12 Nov 2005
First Registration Date:	12 Nov 2005
Transfer Count:	4
Actual ARF Paid:	\$1,114.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	11 Nov 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$6,248.00
COE Rebate Amount:	\$3,604.00
Total Rebate Amount:	\$3,604.00

The information contained herein is correct as at 04 May 2020

OK

JH2NC39975M100040